OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SALAFE	NEW MEXICO OIL CONSERVATION	ON COMMISSION	Effective 1-1-65
FILE		1	5a. Indicate Type of Lease
u.s.g.s.	<u>.</u>		State Fee X
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR			5. State Off & Gas Lease No.
		. <u></u>	
SUNI (DO NOT USE THIS FORM FOR USE "APPLIE	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSA	DIFFERENT RESERVOIR. ALS.)	7. Unit Agreement Name
OIL GAS WELL WELL	OTHER- P&A Drinkard		8. Farm or Lease Name
Name of Operator			
Atlantic Richfield (ompany		R. L. Brunson
. Address of Operator			
P. O. Box 1710, Hobb	s, New Mexico 88240		10. Field and Pool, or Wildcat
Location of Well	w 13	9910	
UNIT LETTER J	2310 FEET FROM THE South LINE	AND FEET FROM	mmilitiinind
THE East LINE, SE	CTION 4 TOWNSHIP 22S RA	ANGE 37E NMPM.	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whether DF, RT,	GR. etc.)	12. County
	3440' GR		Lea
16.			
Chec	k Appropriate Box To Indicate Nature of Intention TO:		REPORT OF:
		· ·	
PERFORM REMEDIAL WORK		IAL WORK	ALTERING CASING
TEMPORARILY ABANDON		NCE DRILLING OPNS.	PLUG AND ABANDONMENT X Drinkard only
PULL OR ALTER CASING		TEST AND CEMENT JOB	
	OTH	ER	
OTHER			
17. Describe Proposed or Complete	d Operations (Clearly state all pertinent details, and	give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.			
was performed in the	s to plug and abandon Drinkard a e following manner: POH w/compl P&A effective 8/28/74.	cone only on 8/28/7 letion assembl y. S	4. Plug and Abandonment et CIBP @ 6935' on WL &
	•		
			•
			`
•			
		•	
18. I hereby certify that the inform	ation above is true and complete to the best of my kn	lowledge and belief.	
	0		
SIGNED HILL	TITLE DIS	t. Drlg. Supv.	
	D.J. n.		
/ /	Drlg. Signed by		
A 202 OVE 0 AV	7 TITLE		DATE

CONDITIONS OF APPROVAL, IF ANY: