

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Shell Oil Company		8. Farm or Lease Name Rinewalt
3. Address of Operator P. O. Box 1509, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER F , 2310 FEET FROM THE North LINE AND 2970 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 22S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3458 DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug & abandon Drinkard zone and open additional pay in Blinebry	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP at 6340' and cap with 35' cement to plug and abandon Drinkard zone.
2. Perforate additional pay in Blinebry with 1 JSPF at 5842, 5819, 5813, 5793, 5767, 5754, 5726, 5718, 5710 and 5700.
3. Acid treat with 6000 gal 15% NE. Place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>James E. Sullivan</u>	TITLE <u>A. E. Cordray Staff Engineer</u>	DATE <u>11-13-72</u>
Orig. Signed by <u>Joe D. Ramey</u> Dist. I, Supv.		DATE <u>NOV 16 1972</u>
APPROVED BY _____		
CONDITIONS OF APPROVAL, IF ANY:		