

COPIES RECEIVED		
DISTRIBUTION		
OFFICE		
FOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-55

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. Well <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Shell Oil Company	8. Farm or Lease Name Rinewalt
3. Address of Operator P. O. Box 1509, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Blinebry

15. Elevation (Show whether DF, RT, GR, etc.) 3460 DF	12. County Lea
--	-------------------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Abandon Paddock and re-enter Blinebry</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well shut in 1-1-73 after plugging back from Blinebry and attempting completion in Paddock.

1. Squeeze Paddock perforations 5151-5209 with 150 sx Class C cement.
2. Drill out cement and CIBP at 5474.
3. Perforate additional Blinebry pay 5461-5932 (35 holes).
4. Acidize, fracture treat and complete as warranted.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>G. W. Tullos</u>	TITLE <u>Senior Production Engineer</u>	DATE <u>9-17-75</u>
APPROVED BY <u>John Ranyan</u> Geologist	TITLE <u>Geologist</u>	DATE <u>9-17-75</u>
CONDITIONS OF APPROVAL, IF ANY:		