Submit 3 Copies to Approriate District

State of New Mexico

Energy, Minerals and Natural Resouces Office DISTRICT I FORM C-103 1625 N. French Dr., Hobbs, NM 88240 Revised March 25, 1999 OIL CONSERVATION DIVISION WELL API NO. DISTRICT II 811 South First, Artesia, NM 88210 2040 South Pacheco 30-025-10036 Santa Fe, NM 87505 DISTRICT III Indicate Type of Lease 1000 Rio Brazos Rd., Aztec, NM 87410 **▼ FEE** STATE State Oil & Gas Lease No. DISTRICT IV 2040 South Pacheco, Santa Fe, NM 87505 24282 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Rinewalt Type of Well: GAS WELL OTHER OIL WELL 2. Name of Operator 8. Well No. 3 Apache Corporation 3. Address of Operator 9. Pool name or Wildcat Drinkard (19190) / Wantz-Abo (62700) DHC-2403 2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400 1980 Feet From The North Line and 1980 West Unit Letter Feet From The **22S** 37E Section Township Range NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3456' Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Plug and Abandon Remedial Work Perform Remedial Work Altering Casing Temporarily Abandon Change Plans Commence Drilling Operations Plug and Abandonment Pull or Alter Casing ☐ Casing Test and Cement Job Other Other Re-open Wantz-Abo / Add Perfs / DHC 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 11/30/99 RIH w/4-3/4" bit on WS. Tag CIBP @ 6660'. Pump 500 bbls 1% KCL wtr to break circulation. Drill out CIBP & 35' cmt. Perforate Wantz-Abo @ 7079, 84, 88, 91, 7100, 02, 09, 11, 15, 19, 7255, 60, 63, 65, 76, 78, 89, 93 @ 1 JSPF 12/1/99 12/2/99 Test tbg in hole to 6000#. Set RBP @ 7300'. Set packer @ 7063'. Acidize new Wantz-Abo perfs w/ 1000 gals 15% BxDx. Release packer and reset @ 6670'. Acidize Wantz-Abo 6714 - 7293 w/ 3000 gals 15% BxDx. Reset RBP @ 6630' and packer @ 6355'. Acidize Drinkard 6405 - 6616 w/ 3000 gals 15% BxDx 12/7/99 Set packer @ 7071'. Acidize Wantz-Abo 7079 - 7293 w/ 1000 gals 15% HCL. Release and reset packer @ 6670' Acidize Wantz-Abo 6714 - 7293 w/ 1000 gals 15% HCL Downhole Commingle of Drinkard and Wantz-Abo pools effective 12/8/99 I hereby certify that the mation above is true and complete to the best of my knowledge and belief. Sr. Engineering Technician SIGNATURE 2/17/00 DATE nderson TYPE OR PRINT NAM TELEPHONE NO. (This space for State Use) S WHILLIAMS APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, IF ANY:

