

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, NM 87504-2088

WELL API NO. 30-025-10043
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Rinewalt A
2. Name of Operator The Wiser Oil Company	8. Well No. 1
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797	9. Pool name or Wildcat Drinkard
4. Well Location Unit Letter D : 560 Feet From The South Line and 660 Feet From The East Line Section 4 Township 22S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3453' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/14/01 MIRU Computalog WL w/mast. Tried to load hole w/hot oil unit, could not. Pump 75 bbls. fresh water w/csg. on vac. TIH w/CIBP & set @ 6250'. Pump 150 bbls. fresh water & load hole. Pressure to 1000#. Csg. leaked back to 0# in 3 min. Ran CBL w/no pressure on csg. Top of cement @ 4500'. RD WL unit. Well is SI pending evaluation.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II DATE January 27, 2002
TELEPHONE NO. 392-9797

(This space for State Use)

APPROVED BY _____

ORIGINAL SIGNED BY
PAUL F. KAUTZ
TITLE PETROLEUM ENGINEER DATE MAR 20 2002