

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 87504-2088

WELL API NO.

30-025-10043

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797

4. Well Location

Unit Letter D : 560 Feet From The South Line and 660 Feet From The East Line

Section 4 Township 22S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3453' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Add Drinkard perms. & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/24/01 MIRU Key Well Service. POH w/rods. Pump parted in pull rod. NU BOP. RIH w/1" & tagged. POH w/tbg. Tagged fill @ 6538'.

4/25/01 RU Black Warrior WL. Loaded hole w/120 bbls. produced water. Ran Neutron-Gamma Ray log.

4/26/01 RIH w/bulldog bailer, 2-7/8" tbg. & 2-3/8" tbg. Cleaned out open hole f/6538'-6555'. POH w/tbg. & bailer.

4/27/01 Perforated Drinkard f/6336', 37', 38', 39', 68', 69', 70', 76'-86', 91', 92', 6400' & 01' w/2 SPF. RD WL. RIH w/RBP & pkr. Set RBP @ 6430' & pkr. @ 6420'. Pressure tested RBP. POH to 6300' & set pkr. Acidized Drinkard perms. 6336'-6401' w/4000 gals. 15% NE-FE acid w/3000# rock salt. Good block action. ATP 2600# @ 4 bpm. MTP 3000# @ 4 bpm. ISIP 400#. 5 min. vac. SI for 1 hr. Released pkr. & retrieved RBP. POH w/tools & tbg.

4/28/01 RIH w/2-3/8" tbg. SN @ 6507'. RIH w/rods & 2" x 1-1/4" x 16' pump. Pressure tested tbg. to 500#. Left well pumping to Battery. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II

DATE August 7, 2001

TELEPHONE NO. 392-9797

(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY
DATE
PETROLEUM ENGINEER

DATE

2001

