OF COPIES RECEIVED	NEW MEXICO OIL CONS	ERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
FILE			5a. Indicate Type of Lease
			State Fee XX
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR			
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICATI	Y NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUG B ON FOR PERMIT - " (FORM C-101) FOR SUC	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	
1.			7. Unit Agreement Name
ALL GAS WELL	OTHER+		
2. Name of Operator			8, Farm or Lease Name
Gulf Oil Corporation			L. I. Baker
3. At tress of Operator			9. Well No.
Box 670, Hobbs, New Mex:	<u>ico 88240</u>		3
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER	2086 FEET FROM THE South	LINE AND 554 FEET FR	OM Drinkard
THE East LINE, SECTION	5 TOWNSHIP 22-5	RANGE 37-E NM	»: () () () () () () () () () () () () ()
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
	34	39' GL	Lea ())))))))
^{16.} Check	Appropriate Box To Indicate N	ature of Notice, Report or (Other Data
	ITENTION TO:	-	NT REPORT OF:
	÷		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	_	COMMENCE DRILLING OPNS.	PLUG AND ABANDONALING STATE
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	y
OTHER Attempted to dual	1 Drinkard and Tubb,	OTHER	<u> </u>
MC-2097			ing estimated date of starting any prop

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop-estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated view (Clearly state all pertinent details, and give pertinent dates, including estimated view (Clearly state all pertinent dates, and give pertinent dates, including estimated view (Clearly state all pertinent dates, including estimated view (Clearly state all pertinent dates, and give pertinent dates, including estimated view (Clearly state all pertinent dates, and give estimated view (Clearly states, and give estimated view (Clea

6423' PB.

Pulled producing equipment. Squeezed Drinkard perforations 6435' to 6580' with 200 sacks of Class C cement with 2700#. Perforated Drinkard zone in 7" casing with 4, 1/2" JHPF at 6364-66', 6387-89' and 6412-14'. Ran treating equipment and treated new perforations with 3500 gallons of 15% NE acid and frac treated with 8000 gallons of gel water and 15,000 gallons with 1# SPG. Maximum pressure 5400#, minimum 3600#, ISIP 2200#, after 15 minutes 1750#. AIR 12 BPM. Swabbed and tested. No indication of commercial production.

Plans have now been made to abandon Drinkard zone and complete as a single producer in the Tubb as follows: Pull treating equipment. Set CI BP at 6310' and cap with 10' cement. Perforate Tubb zone in 7" casing in the approximate interval 5998' to 6240'. Treat new perforations with 3000 gallons of 15% NE acid and frac treat with 40,000 gallons of gel water. Swab and clean up and return well to production.

18. I hereby certify that the	information above is true and com	plete to the best of my knowledge and belief.	
SIGNED	andrah	TITLE Area Engineer	DATE November 1, 1974
APPROVED BY	Orig Stand by Jos D. 25-34		DATE