


FORM C-105



NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico Santa Fe, New Mexico WELL RECORD

Mail to Oil Conservation Commission, Santa Fe, New Mexico, er its proper agent not more than twenty days after completion of well. Follow instructions in the Rules and Regulations of the Commission. Indicate questionable data by following

LOC	AREA 640 ATE WELL	ACRES CORRECTLY	I			RIPLICATE, FORI PROPERLY FILLI		NOT BE AI	PROVED
Gulf	Oil Co					Box 166	7, Hobbs,	New Me	xico
Lee S			perator .Well No	4	in NW	NEof S			r 22 S
		N. M. P. M.,							County.
									n5
	•					ment No			
								-	ew Maxico
		**		*					Texas
			_						19 51
									•
		level at top o							
The infor	mation giv	ven is to be ke	ot confider		SANDS OR	zones	1	9	
•									
No. 3, fro	m	•••••	to	······································	No.	6, from	••••••	to	
					TANT WATE				
		e of water infle					at.		
-									
				C	ASING RECO	RD			
	WEIGHT	THREADS		AMOUNT	KIND OF	CUT & FILLED	PERFO	RATED	PURPOSE
SIZE	PER FOO	T PER INCH	MAKE	AMOUNT	SHOE	FROM	FROM	то	PORPOSE
13 3/8	48#	8 R.T	SS	2851					
9 5/8	36#	& R.T	SS	27861					
-									ļ
7"	26#	8 R.T	S3	64961					
			M	UDDING A	ND CEMEN	ring record			,
SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SAC	KS ENT ME	THODS USED	MUD GR	AVITY	AMOUN	T OF MUD USED
17_1/4_3	3 3/8	3011	310						
2 1/4	9 5/8	13001	1300	l l					
8 3/4	7	65091	700						· · · · · · · · · · · · · · · · · · ·
				PLUC	S AND ADA	PTERS			
Heaving	plug—Ma	terial			Lengt	h	Der	th Set	
Adapters	Materi	al	••••••		····	Size			
			RECORD	OF SHOO	TING OR CH	IEMICAL TREA	ATMENT	····	
SIZE	SHEL	L USED	EXPLOSIV CHEMICAL	E OR USED	QUANTITY	DATE	DEPTH 8 OR TREA	HOT DE	PTH CLEANED OUT
						•			
	<u> </u>			!		l	<u> </u>	, [
Results of	f shooting	or chemical							
***************************************	•••••								
•						ND SPECIAL T			
If drill-ste	em or othe	er special tests	or deviati	on surveys v	were made, su	bmit report on	separate sh	eet and att	ach hereto.
					TOOLS USE	D			
									feet
Cable too	ls were u	sed from						feet to	feeı
Dut to	oducie				PRODUCTIO	'n			
						ls of fluid of wh	ichaa	% was	oil;%
Rock pres	ssure, lbs.	per sq. in		***************************************					
					EMPLOYEE				
Gulf-(il Cor	_							Driller
				-					, Driller
		ffirm that the determined fro	informati	on given he		I OTHER SID		f the well a	nd all work done on
						HobbaNa	w Marian	Ма	Peh-231951
									Date -
//	-	,	'10	elat	Po				
· u	vZ	1 1 5 %	van	lotary Public	Re	presentinggu			OM.
•							Coph	hana or Obe	71 8 DOT

My Commission expires......7-20-54

Address Box 1667, Hobbs, New Mexico

Sharfnes cand and shale 1327 1799 1979 1277 1277 1277 1277 1277 12		FORMATION		THICKNESS IN FEET	то	FROM
Annydrito 2150' Salt (Ease) 2450' Tates 2640' So A Andres 3850' Glorista 5123' Briokard 6520' Othory for Pay 6520' - 6585'		ele sait	hed bed and sind bed and sind bed and shale shale and shale time line and shale		432* 775* 999* 1738* 1937* 2472* 2860* 4019* 4145*	01
Ankydrato 1170° Talk (Base) 2450° Tates 2640° Ca A Andres 3850° Glarieta 5125° Ilrickard 6520° 3H. AND Day P.Y. 6520° - 6565°				<i>;</i> .	4	- 1
Tates 2640 in a Madras 3850 ideorieta 5125 Drinkard 6520 OH 650 - 65651		TOPS	POWATLA		•	:
63201 - 65851		2450* 2640* 3 89 0*	Salt (Dame) Yates Sa n Abdres			
		& PAY	OIL AND G			
		6520' - 65 85'	**			
			1		-	
			e de la companya de		·	
				2.14		
		•				

				<i>;</i>		
				:		
	a de la companya de l					
		. 8	a de la companya de			

y^