

CONSERVATION DIVISION

P. O. BOX 2

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

0+6-NMOCD-Hobbs 1-Laura Richardson-Midland
1-File 1-JA
1-Engr PJB 1-BB
1-Foreman CRM

5a. Indicate Type of Lease	
State ☐	For ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name B.A. Christmas Cowden
3. Address of Operator P.O. Box 730, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>2200</u> FEET FROM THE <u>North</u> LINE AND <u>880</u> FEET FROM THE <u>East</u> LINE, SECTION <u>5</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	CEMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/19/83 TD 6568'. 5 1/2" @ 6476'. Rig up. Perfs @ 6422-6471'. Pull pump.
8/20/83 Pull tbq. Ran plug and pkr. Set pkr @ 6264'. Locate hole in 5 1/2" csg @ 4902'-4865'. 1/2 bbl min 1200#, 700# test above.
8/21/83 Set retainer @ 4772'. Squeeze holes 4902-65'. Howco w/ 150 sxs class "C", 3# salt, 2000# 2 1/2 BPM. Displace to 4772, 2000#. Pull out. Reverse out 3 sxs.
8/22/83 Ran 4 3/4" bit, drill @ 4770', 2' cement & retainer to 4775', hard cmt to 4820'.
8/23/83 Pull bit, ran 4 3/4" bit and drilled 4820-5038'.
8/24/83 Test w/ 500#. Drl cmt 5039-5351'.
8/25/83 Drlg cmt 5321-5536'. Still in cmt.
8/26/83 Drlg cmt 5536-5673'. Test to 550#, OK. Ran bit to 6260. Wash sand to 6264'. Pull bit. Ran retrieving tool. Pull bridge plug to 3500'.
8/27/83 Pull bridge plug. Ran 4 3/4" bit and tagged fill @ 6528'. Clean out to 6568' = TD. Pull bit.
8/29/83 Ran 206 jts 6354'. 2 3/8" tbq, set @ 6399'. SN @ 6364'. Ran 2" x 1 1/2" x 16' pump. Rig down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Superintendent DATE August 30, 1983
D.R. Crockett

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ DATE SEP 2 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 2 1983

O.C.D.
INQ825 OFBC