## STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT

## C CONSERVATION DIVISION

CAST AND MINICE	C CONSERV	A HON DIVISION		Form C-103 ·
	P. O. f	BOX 2088		Revised 10-1-78
POITRIBUTION	CANTA FE N	EW MEXICO 87501		
SANTA FE	SANTATE		5a. Indicate Ty	pe of Lease
PILE			State	F•• 🔀 📗
U.S.O.S.		•		Gas Lease No.
LAND OFFICE			S. Sidie Oir &	
OPERATOR				mmmm
				VIIIIIIIII
SUNDRY	Y NOTICES AND REPORTS	ON WELLS		//////////////////////////////////////
(DO NOT USE THIS FORM FOR PROP USE "APPLICATION	Y NOTICES AND REPORTS POSALS TO CHILL OF TO OFLPEN OF PL ON FOR PERMIT - 11 (FORM C-101) FOR	SUCH PROPOSALS.	7. Unit Agreen	ient Name
				1
OIL 🔻 6AB	OTHER-		8. Form of Lea	ase Name
well [A] Will [			i "	\$
Name of Operator Sohio Petroleum Company				zzell.
	zum Company		g. Well No.	
Address of Operator		-4 Toxas 79705	1	
10 Desta Dri	ve, Suite 600W Midlar	nd, lexas 73703	10. Field and	Pool, or Wildcat
Location of Well			i	1
G	1760 No.	rth LINE AND 1760	PEET FROM Blin	THIN THIS
UNIT LETTER	PEET PROM THE			
East	5	22-S 37-E	имрм. () () ()	
LINE SECTION	ON YOWNSHIP	RANGE	////////////////////////////////	
THE			12. County	
mmmm	15. Elevation (Show wh	3447 DF	Lea	
	T- India	ate Nature of Notice, Repo	rt or Other Data	. •
Check	Appropriate Box 10 marca	SUBS	EQUENT REPORT	OF:
NOTICE OF I	NTENTION TO:	33.24		
	•		<b>┌</b> ┐	LTERING CASING
$\square$	PLUS AND ABANDON	NEMEDIAL WORK		US AND ABANDONMENT
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPNS.	<b> </b>	.ue And Adamson [
TEMPORABILY ARANDON	CHANGE PLANS	CASING TEST AND CEMENT JO	• 🔲	. $\square$
PULL OR ALTER CASING	CHARGE	OTHER		
07 H C A				
	- I U nostin	ent details, and give pertinent dates	, including estimated dat	e of starting any proposed
17. Describe Proposed or Completed C	operations (Clearly state all pertin	EM GCSCSSC CO.		
WORLD SEE RULE				
1.) 2-14-85 Set CIBP	at 6250' and cap with	h 35' of cement.		•
- > 0 1/ 05 Cot CTRP	at SSOUL AND CAD WILL	II JJ OI COMONO		
3.) 2-14-85 Set CIBE	sacks at 2870' and ta	o at 2560'.		· •
	sacks at 2070 and to	8 44		
5.) 2-19-85 Pump 40	sacks at 1000'.			
6 ) 2-19-85 Pump 40	sacks at 161'.			
7.) 2-19-85 Pump 10	sacks at surface.			
7.7 2 25 00 1				
·				
				***
				•
•				
				<del></del>
	- d acomplete to	the best of my knowledge and belief	• •	
	ton about in true and complete to	• • • • •		

OIL & GAS INSPECTOR

...APR 2 3 1985

MAR 18 185