Π	UPLICATE ALCO OIL	· · · · · · · · · · · · · · · · · · ·	Revis
		CONSERVATION COMMISSION FE. NEW MEXICO	
	(File the original and 4 cop	FE, NEW MEXICO HUBBS OFFICE OCC ies with the appropriate district	office)

## CERTIFICATE OF COMPLIANCE AND A UTHORISATION TO TRANSPORT OIL AND NATURAL GAS

Company or Operator_	Skelly Oil Company	Lease R.W. Grissell
Well NoUn	it Letter * S 6 T 228	R 372 Pool Penrose-Skelly
CountyLea	Kind of Lease (State	e, Fed. or Patented) Petented
If well produces oil or	condensate, give location of	tanks:Unit 🛴 S 💪 T 228 R 378
Authorized Transporte	r of Oil or Condensate	thell Pipeline Company
Address	Hobbs, New Mexico	
(Give addr	ess to which approved copy	of this form is to be sent)
Authorized Transporte	r of Gas Skelly Gaseli	ne Plant
Address	ess to which approved copy	ierie
	, give reasons and also exp	ann its present disposition:
Reasons for Filing:(Ple	ease check proper box) N	New Well ()
Change in Transporter	of (Check One): Oil ( ) Dry	y Gas ( ) C'head ( ) Condensate ( )
Change in Ownership	( ) Oth	er(Give explanation below)
Remarks:		(Give explanation below)
Casinghead	Gas Commection.	
The undersigned certiformission have been com	ies that the Rules and Regulaplied with.	ations of the Oil Conservation Com-
Executed this the 224.	day of October 19 56	
Approved OCT 4	1000	tle Dist. Supto
By ( . M		ldress Bex 38
	er District I	Hobbs, Hear Mexico

Sidemanifero e e o grandina de la gr

I will small the second of the second second

and the second s

EAL SEC 9

greens entire? liefs

courses ferrium

Skelly Jasolnee Slant Stantise, see Sontao

The state of the s

and, and the control of

भूतवार व्यवस्त्र

Markey for the Miller of the Mills

**₹**0.06

oralises west weather.