

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator SOHIO PETROLEUM COMPANY 3. Address of Operator P. O. Box 3000, Midland, Texas 79701 4. Location of Well UNIT LETTER 0 , 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 22S RANGE 37E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3426'	7. Unit Agreement Name 8. Farm or Lease Name Mattern 9. Well No. 5 10. Field and Pool, or Wildcat Arrowhead, Grayburg 12. County Lea
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. **This well was temporarily abandoned December 1958, uneconomical to produce.**

PROPOSED WORK:

Set 100' cement plug above 3414 - 3710' open hole, plug from 3314-3414'.
Cut off 7" casing about 1500'.
Place 100' cement plug 1450 - 1550' (50' in and 50' out of casing).
Place 100' cement plug above salt, 993' - 1093'.
Place 100' cement plug 50' in and 50' out of surface, 995' - 1095'.
Place 10 sack cement plug at surface.
Mud laden fluid to be placed between plugs.
This work will start on or before 10-1-75.

Expires 12/1/75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. H. Walters J. H. Walters TITLE District Superintendent
Midland District DATE December 4, 1974

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

REMOVED

DEC 14 1974

OIL CONSERVATION COMM.
HOBBS, N. M.