

SE

ION


Penrose

ern

Well No. 1

te

Range 37 County L



Company

Roman Penrose

Farm Name

Matern

Well No.

Land Classification

Stat 4

Sec.

7

Twp. 22

Range 37

County Lea

Feet from Line:

N. 1650 S.

E. 330 W.

Elevation

Method

Contractor

Co Look Not

Scout

Spudded

9-17-39 Completed

Initial Production

Bond Status

ACID RECORD

Casing and Cementing Record

Size	Feet	Inches	Sax Cement
8 1/8	330		125
8 1/4	330		125

Gals.

Prod.

Date _____

Prod.

Date _____

Top Pay

Total Depth

SHOOTING RECORD

No. of Quarts

Shot at

Feet

No. of Quarts

Shot at

Feet

[illegible]

LOG

[illegible]

**SCOUT REPORT
NEW MEXICO
OIL CONSERVATION COMMISSION**

SE

N

S

W

E

Company Rouge Penrose
 Farm Name Mattern Well No. 1
 Land Classification State
 Sec. 7 Twp. 22 Range 37 County Lea
 Feet from Line: N. 1650 S. E. 330 W.
 Elevation _____ Method _____
 Contractor C. Cook Ret Scout _____
 Spudded 9-17-39 Completed 10-5-39 Initial Production _____
 Bond Status _____

ACID RECORD

**Casing and Cementing Record
Amount**

Size	Feet	Inches	Sex Cement
<u>8 1/8</u>	<u>330</u>		<u>1 1/2</u>
<u>5 1/2</u>	<u>3631</u>		<u>400</u>
<u>2"</u>	<u>3740</u>		

Gals.	Prod.	Date
	Prod.	Date

Top Pay 3631

Total Depth

SHOOTING RECORD

No. of Quarts	Shot at	Feet
No. of Quarts	Shot at	Feet

Date		Date	
<u>8-16</u>	<u>Loc</u>		
<u>8-23</u>	<u>✓</u>		
<u>9-13</u>	<u>✓</u>		
<u>SEP 20 1939</u>	<u>Ø 900 RR</u>		
<u>SEP 27 1939</u>	<u>Ø 2995 A</u>		
<u>OCT 4 - 1939</u>	<u>TV 3664 L</u>		
<u>OCT 11 1939</u>	<u>TD 3750 L</u>		
	<u>TP flow 10 BOPH</u>		
	<u>Chm 2" tubing</u>		

[illegible][illegible]