



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

BRUCE KING
GOVERNOR

POST OFFICE BOX 1980
HOBBS, NEW MEXICO 88241-1980
(505) 393-6161

TO WHOM IT MAY CONCERN:

August 13, 1992

CORRECTION OF SURFACE LOCATION

Chevron USA Inc.
H.T. Mattern #2 (API #30-025-10098)
Section 7, T22S, R37E
from: 1650/S & 1650/W
to: 1650/S & 1563/W

This well had previously been changed to the Chevron USA Inc. Arrowhead Grayburg Unit #201, but wellbore was unsatisfactory for unit well so well was plugged and Chevron drilled a new Unit well #201 at 1650/S & 1650/W of Sec. 7, T22S, R37E

The incorrect location of the H.T. Mattern #2 was due to the fact that the original measurements were referred to as 330' north of South line and 330' East of West line of the SW of NE of SW of Sec. 7, T22S, R37E. When these measurements were transferred to OCD forms which required measurements from the section line instead of the quarter/quarter lines they were recorded incorrectly because Unit letter "L" of Section 7 is not a standard size lot.

The corrected location is taken from measurements furnished by John West Engineering when they surveyed for the new Arrowhead Grayburg Unit #201.

See inset on attached plat.

Jerry Sexton
Supervisor, District I

