

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator William B. Yarborough | 8. Farm or Lease Name L. E. Grizzell |
| 3. Address of Operator 200 N. Loraine - Suite 1400, Midland, Texas 79701 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>22-S</u> RANGE <u>37E</u> NMPM. | 10. Field and Pool, or Wildcat Penrose Skelly Grayburg |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3435 KB | 12. County Lea |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/28/89 thru 12/1/89

1. Reperforate Penrose Skelly GB w/20 holes @ 3440', 42, 71, 75, 77, 3509, 18, 20½, 25, 30, 60, 91, 3604, 26, 30, 65, 93, 3710, 31 & 33'.
2. Acidize in five stages using packers to isolate w/a total volume of 2100 gal. 15% HCL 300 gal Ziolene, 5 gal emulsifier and 11 gal sequestering agent.
3. Make 29 swab runs. Last 5½ hrs, swabbed 6BO, 27 BW.
4. Prep. to install pumping equipment for pumping test. Prior to work, well was shut-in.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William B. Yarborough
William B. Yarborough
ORIGINAL SIGNATURE COPY SENTON

TITLE Operator

(915) 684-8578

DATE 12-12-89

APPROVED BY _____

TITLE _____

DEC 21 1989

CONDITIONS OF APPROVAL, IF ANY: