## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

The second of th						
(	T					
DISTRIBUTION		1				
BANTA FE	ī	1				
FILE	T	1				
U.1.G.X.	$\neg$	1				
LAND DEFICE	ī	T				
OPERATOR	1	i				

## OIL CONSERVATION DIVISION

DISTRIE	UTION	Ì	P. C. 8	OX 2088			Form C-103
BANTAFE	1 1	1	SANTA FE, NE		- 4 -		Revised 19-1-
FILE	1 1	1		W WEYICO 87	501		
U.1.G.1.	11	1				Sa Indicate Ty	pe c: Lease
LANG DEFIC		1 .		" <del>~</del> .		State	Fee X
DPERATOR		1				S. State Oti & C	
		•					
	SUMPE	NOTICES	AND DEDOCATE O			kaman	· · · · · · · · · · · · · · · · · · ·
(DO MOT US	SUNUM For Post Post Post	CT NUTICES	AND REPORTS C				
	USE "APPLICAT	IO- FO- PE-LIT.	-" (FORM C-101) FOR 1	U(# PROPOSALE.)		111111111111111111111111111111111111	
er [☑]	EAS					7. Unit Agreeme	ent Name
Zit. X	were L	CTHER-				l.	
i. Name of Operator						8. Fem or Leas	se liame
SHELL WEST	ERN E&P INC.					1	
. Address of Opera				<del></del>		GRIZZELL	<u>.                                    </u>
P O ROX	576 HOUSTON	TEYAC 77	7001 (WCK 443	٤١			
Location of Well	570, 110051011	, ILAAS //	001 (MCK 443	<u> </u>		1 6	
2000		20001				10. Field and P	ool, or Windows
UMIT LETTER	<u> </u>	2200.	SOUT	H 4:	20	DRINKARI	)
					/EET /RO.	milling	mmmi
EAS	T	. 8	70WHSHIP 22	-S :	37_F		:////////////
		·	TOWNSHIP	RANGE	<u> </u>	.////////	
mmm	mmm	in this	Elevation (Show whesh	DE ET CD		(11111111111111111111111111111111111111	<u> inninini</u>
		//////		er Dr. KI. GK. Etc.)		11., County	VIIIIII.
6.	<u> </u>	77777	3407' GR			LEA	
	Check.	Appropriate	Box To Indicate	Nature of Notic	e Report of Or	her Dara	
_	NOTICE OF IN	TENTION T	0:	1			
	•				SOBSECUEN	T REPORT OF	:
PERFORM REMEDIAL			_	- [			
PERPOND REMEDIAL			PLUC AND ABANDON	NEMEDIAL WORK	· <u></u>	ALTE	RING CASING
TEMPORABLET ABAND	•			COMMENCE DRILLS	MG DFW3.	≯دuد	THE ABANDONAL INA
PULL OR ALTER CASE	1#C		CHANGE PLANS	CASING TEST AND			<b>-</b>
				OTHER INST	ALLED PLUNGER	R LIFT, RECO	MPLETED TO TX
01=£#				DRIN	KARD, ACD & I	HC'D W/BLIN	IFRRY
				- <u>}</u>	(DHC-61	フト	
7. Describe Propos	ed or Completed Op	perations (Cleari	y state all pertinent d	esails, and give persis	neni daies, includini	estimated date of	* *******
	<del>-</del>						
2-03-86:	Set collar	stop @ 620	06'. Installe	d plunger lif	t and returne	ed well to p	roduction.
				, ,			
3-19-86: Pulled collar stop @ 6206'. Closed sliding sleeve valve @ 6241'. Ran fishing						fichina	
tool - unable to pull blanking plug in "J" Nipple @ 6272'. Opened sleeve, set						risning	
	collar ston	left we	all flowing to	9 111 0 Mipp	16 6 0717	obelied 2166	ve, set
-	00.101 500p	. Lere we	in flowing to	Dall.			
4-08-86:	Dulled coll	3.5 a t a 0	L7 1.3				
4-00-00.	Pulled Coll	ar Stop &	blanking plug	, closed slid	ing sleeve.		
4 11 06	D DUD C						
4-11-86:	Ran BHP of	Drinkard.	Acd Drinkard	perfs 6418' -	- 6511' w/300	gals 15% H	C1-NEA.
							•
4-12-86:	Opened slid	ing sleeve	@ 6241'. Se	t collar ston	0 6210' St	arted well	producing
	as a downho	le commina	led Blinebry/	Drinkard produ	icar thru nlu	nach lift o	producing
			rea or mesigy	or mikara prode	acer cira pro	nger inte	quipment.
						•	
						_	
&. I hereby cently	that the information	above is true as	nd complete to the bea	of my based of	4 5 . 12 . 7	•	
1	~ / · · ·	400 41		: m; snowledge an-	2 D41341.		
4/	1 110	_					•
	Willed for	A, J, F(	ORE TITLE SU	PERVISOR REG.	& PERMITTIN	G JUNE	16, 1986
<del></del>	)						

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

.... JUN 2 0 1986