Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

	~~~ · · · · · · · · · · ·			
P.O. Box 2088				
	1.0.20.20.			
Canta Fe	New Mexico	87504-2088		

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA P.O. Bo		WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Me		5. Indicate Type of Lease SI	ATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease N	<del></del>
SUNDRY NOTIC ( DO NOT USE THIS FORM FOR PROF DIFFERENT RESERV (FORM C-1)	7. Lease Name or Unit Agreement Name			
1. Type of Well:  OIL GAS WELL X WELL	OTHER		GRIZZELL	
2. Name of Operator SHELL WESTERN E&P INC			8. Weil No.	
3. Address of Operator P. O. BOX 576, HOUSTO	<u>.</u>	CK 4435)	9. Pool name or Wildcat BLINEBRY OIL	& GAS
4. Well Location		TH Line and 16	50 Feet From The	EAST Line
Section 8	Township 22S 10. Elevation (Show w	Range 37E whether DF, RKB, RT, GR, etc.)	NMPM L	EA County
11. Check A NOTICE OF INTI	* * -	cate Nature of Notice, R	eport, or Other Data SEQUENT REPO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	ING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	GOPNS. PLUG	AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
OTHER:		OTHER: Acd	E CU Paraffin	×
12. Describe Proposed or Completed Operation work) SEE RULE 1103. 6-02 to 6-13-89: PDH w/prod equip. CO perfs 5407'-5921'. So (80% 20% HCI, 20% XY)			·	
to prod.				· .
6-28-89: Chag out prod equip.	Retd to prod.			:
Chag out production	, F			•
			•	
I hereby certify that the information above is true	and complete to the best of my know	ledge and belief.		
SIGNATURE AAAMU	thema	REGULATORY S	SUPV.	TE 7-28-89
TYPE OR PRINT NAME J. H. SMIT	HERMAN	(7	713) 870-3797 TE	LEPHONE NO.
(This space for State Use) ORIGINAL SIGNED				AU6 kg 1 1989

CONDITIONS OF APPROVAL, IF ANY: