

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Humble Oil &amp; Refining Company</b>	8. Farm or Lease Name <b>J. L. Greenwood</b>
3. Address of Operator <b>c/o Hobbs Pipe &amp; Supply Company, Box 2010, Hobbs, N.M.</b>	9. Well No. <b>6</b>
4. Location of Well UNIT LETTER <b>0</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1981</b> FEET FROM THE <b>East</b> LINE, SECTION <b>9</b> TOWNSHIP <b>22-S</b> RANGE <b>37-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Penrose Sky Grayburg</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3423' D.F.</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 50 sx cement plug from 3500'-3715'.
2. Spotted a 10 sx cement plug from 0-35'.
3. Hole was loaded with mud laden fluids.
4. Well was plugged and abandoned on 11-10-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. Schneider* TITLE Agent DATE 12/3/70

APPROVED BY *John W. Runyan* TITLE Geologist DATE JUL 19 1971  
CONDITIONS OF APPROVAL, IF ANY: