

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>3002510136</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <b>FEE</b>
7. Lease Name or Unit Agreement Name <b>J L GREENWOOD</b>
8. Well No. <b>15</b>
9. Pool name or Wildcat <b>BLINEBRY OIL &amp; GAS</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORMC-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator <b>EXXON CORPORATION</b>
3. Address of Operator <b>ATTN: REGULATORY AFFAIRS ML#14 P. O. BOX 1600 MIDLAND, TX 79702</b>	4. Well Location Unit Letter <b>M</b> : <b>760</b> Feet From The <b>SOUTH</b> Line and <b>660</b> Feet From The <b>WEST</b> Line Section <b>9</b> Township <b>22S</b> Range <b>37E</b> NMFM <b>LEA</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3413 DF</b>	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **SQZ PADDOCK/RECOMPL BLINEBRY** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/15/95 MIRU, BEGIN CO WELL  
12/19/95 SQZ PADDOCK 5042-5178 W/100 SX C  
12/21/95 DUMP BAIL 35' CMT ON CIBP @ 6150; PERF 5622-5764 1 SPF  
12/22/95 ACID 5622-5764 2646 GAL 15% HCL FRAC W/44900 GAL+169000# 20/40  
12/28/95 PERF 5409-5525 1 SPF ACID W/1932 GAL 15% HCL  
12/29/95 SET RET @ 5380 SQZ BLINEBRY PERFS W/75 SX H  
12/30/95 SET PKR @ 4900 SQZ W/75 SX H DO TO CIBP @ 5533  
01/04/96 REPERF UPPER BLINEBRY 5409-5449 1 SPF 61 HOLES  
01/06/96 ACID 5409-5525 W/794 GAL 15% HCL; FRAC W/20000 GAL+66000# 20/40  
01/09/96 MILL, PUSH CIBP DOWN TO 6009', CIRC CLEAN  
01/10/96 RIH W/PROD EQUIPMENT, WELL READY TO PRODUCE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Julie H. Mitchell TITLE Staff Office Assistant DATE 02/08/96  
TYPE OR PRINT NAME Julie H. Mitchell (915) 688-7888 TELEPHONE NO.

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

MAR 21 1996

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: