

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 061446

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pearosa

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Brunson, Ellenburger

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 9, T22S, R37E, N.M.P.M.

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SOHIO PETROLEUM COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 3000, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1874' FNL and 766' FWL.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3428' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

Plug and Abandon X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This is an open hole completion in the Ellenburger. Last production was 3-20-64. Un-economical to produce. Casing will be chemically cut. Plugs will be placed by pump. Well will be closed in accordance with ~~N. M. S. C. C.~~ regulations.
U. S. G. S.

PROPOSED WORK:

Set 100' cement plug above 8089'-8120' open hole, plug from 7989'-8089'.

Cut off 7" casing about 3000' (surface pipe set at 2785').

Place 100' cement plug 2950-3050' (50' in and 50' out of casing).

Place 100' cement plug 50' in and 50' out of surface, 2735'-2835'.

Place 10 sack cement plug at surface.

Mud laden fluid to be placed between plugs.

This work will start on or before 10-1-75.

SEE ATTACHED FOR ADDITIONAL REQUIRED PLUGS

18. I hereby certify that the foregoing is true and correct

SIGNED

J. H. Walters
J. H. Walters

TITLE

District Superintendent

Midland District

DATE

December 4, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED
AS AMENDED
JUN 13 1975
ARTHUR R. BROWN
DISTRICT ENGINEER**

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

647-485

