

to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-10160	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ROLLON BRUNSON	
8. Well No. 3	
9. Pool name or Wildcat PADDOCK	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter <u>B</u> : <u>554</u> Feet From The <u>NORTH</u> Line and <u>1874</u> Feet From The <u>EAST</u> Line Section <u>10</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3400' GL	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CMT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELL AS FOLLOWS:

13-3/8" @ 294, CMT W/300 SX, CIRC. 9-5/8" @ 2800 W/1300 SX, TSITOC @ 1305, 7" @ 5234 CMT W/ 500 SX, TSITOC @ 3020.

PLUG #1 CIBP @ 5035 W/30 SX PLUG ON TOP. (COVERS PADDOCK PERFS 5060-5190 & GLORIETTA)

PLUG #2 60 SX PLUG 3590-3900 (COVERS SAN ANDRES & GRAYBURG)

PLUG #3 30 SX PLUG 3200-3350 (COVERS QUEEN) CUT 7" CSG @ 2800' & PULL

PLUG #4 80 SX PLUG 2700-2900 (COVERS 9-5/8 SHOE & 7" CUT TOP) CUT 9-5/8" @ 1200' & PULL

PLUG #5 100 SX PLUG 1100-1300 (COVERS 9-5/8" TOP)

PLUG #6 100 SX 200-300 (COVERS 13-3/8 SHOE) TAG

PLUG #7 20 SX SURFACE PLUG

P&A MUD BETWEEN EACH PLUG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 4/27/93

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY DEPT. OF ENERGY TITLE SECRETARY DATE APR 30 1993

CONDITIONS OF APPROVAL, IF ANY: