SURDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR MALES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR MALES AND REPORTS ON WELLS.	Sa. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FOREFUL OF THE PRINCIPLE OF THE PROPERTY OF A DIFFERENT RESERVOIR. 100 NOT USE THIS FOREFUL OF THE FROMET OF THE ORDER SUCH CHOCK SUCH CHOCK SALES.)	5, State Off 6 Gas Le me No.
OIL X GAS WILL OTHER.	7. Unit Agreement time South Penrose Skelly U
Gulf Oil Corporation Address of Cretator	8. Form of Lease Hame
Box 670, Hobbs, New Mexico 88240	9. Well 130.
, Location of Well	10. Field gad Poot or 2014 at
UNIT LETTER G 1980 FEET FROM THE NORTH LINE AND 1980 FEET	Penrose Skelly
THE East 10 22-S 37-F	MPM.
15, Elevation (Show whether DF, RT, GR, etc.)	12. County
3413' GL	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or NOTICE OF INTENTION TO: SUBSEQUE	Other Data ENT REPORT OF:
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
EMPORARILY ABANDON COMMENCE DRILLING OFNS.	ALTERING CASING PLUG AND ABANDONMENT
CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1703.	ves and filled cellar.
Installec valves above ground level off each casing string. Insperience in Filled cellar.	ected by Mr. N. E. Clegg.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. Three Area Engineer	'page February 2, 1976

INDITIONS OF APPROVAL, IF ANY: