

ALL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BRUNSON-ARGO Well No. 17

Field: DRINKARD

County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

BBL'S/MIN AND USE 700 LBS OF BENZOIC
ACID FOR SELECTIVITY. INJECT 175 LBS
OF BENZOIC ACID AFTER EACH 1,000 GALS
OF ACID.

5. SWAB AND TEST THE WELL AS REQUIRED.

NOTE: ALL KILL WATER SHOULD BE MANUFACTURED
SALT WATER TREATED WITH 2 GALS OF ADMALL
PER 1,000 GALS OF WATER.

6. RETURN THE WELL TO PRODUCTION AS A DRINKARD OIL
AND GAS WELL.