NO. OF COPIES RECEIVED			
DISTRIBUTION			Form C-103 Supersedes Old
SANTAFE			C-102 and C-103
FILE		SERVATION COMMISSION	Effective 1-1-65
U.S.G.S.			
LAND OFFICE			5a. Indicate Type of Lease
OPERATOR			State Fee Y
			5. State Oll & Gas Lease No.
SUN	DRY NOTICES AND REPORTS ON		
(DO NOT USE THIS FORM FOR USE "APPLIC	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG CATION FOR PERMIT -** (FORM C-101) FOR SU	N WELLS BACK TO A DIFFERENT RESERVOIR.	
••		TH PROPOSALS.)	
OIL GAS WELL WELL	OTHER-		7, Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
Skelly 011 Company			
Skelly O11 Company 3. Address of Operator			Baker ¹¹B¹¹ 9. Well No.
P. O. Boy 1351 Midler	d 70701		5. Well 140.
P. O. Box 1351, Midlar 4. Location of Well	a, rexas /9/01		10. Field and Pool, or Wildcat
	660		
	660 FEET FROM THE SOUT	LINE AND FEET FROM	Drinkard
LINE, SEC	TION 10 TOWNSHIP225_	RANGE 37E NMPM	-
	15. Elevation (Show whether	DE RT CR ata 1	<u> </u>
		51, 11, 01, 11.)	12. County
16. Cl		3714' DF	
Check	Appropriate Box To Indicate N	Nature of Notice, Report or Ot	her Data
NUTICE OF	INTENTION TO:		T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	[
OTHER - Squeeze Drinkar	d perfs. 6438-6536' andX		
Padoek perfs. 5060-51	121 and treat Drinkard pe Operations (Clearly state all pertinent det		
work) SEE RULE 1103.	Sperations (Crearly state all pertinent det	ails, and give pertinent dates, including	estimated date of starting any proposed
This well was complete	d as a dual producing thr	ough Paddock perforation	18 5060-51121 anonatal
by Exxon Oil Company,	and through Drinkard perf	orationa 6372_6425! 643	19.45261
- • •	Jan Politica		0-000 ·
The following work is	proposed for this well:		
_	· · · · · · · · · · · · · · · · · · ·		
4 X X			

- Move in workover rig. Pull dual rods and tubing. IJ 2)
- Squeese lower Drinkard perfs. 6438-6536' with 200 sacks cement. 3)
- Squeese Paddock perfs. 5060-5112' with 200 sacks cement.
- Test squeezed Drinkard perfs. 6438-6536' and Paddock perfs. 5060-5112'. 4)
- Treat Drinkard perfs. 6372-6425' with 62,000 gallons gelled brine and 75,000# 20/40 sand. 5)
- Clean out to 6425', if necessary. 6)
- Return well to producing status flowing or pumping Drinkard perfs. 6372-6425'. 7)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Sig	ned) D. R. Crow D. R. Crow	TITLE Lead Clerk	
APPROVED BY	C. 3. Signed by John Runyan Geologist	Geologie	
CONDITIONS O	F APPROVAL, IF ANY:		