

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission, in accordance with the instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other) Gun Perforating	X

8-12-53
(Date)

Hobbs, New Mexico
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Humble Oil & Refining Company
(Company or Operator)

M. G. Penrose
(Lease)

J. P. (Don) Gibbins
(Contractor)

Well No. **2** in the **SE** $\frac{1}{4}$ **NE** $\frac{1}{4}$ of Sec. **13**

T. **22S**, R. **37E**, NMPM, **Lea** County.

The Dates of this work were as follows: **8-12-53**

Notice of intention to do the work (was) (~~was~~) submitted on Form C-102 on **8-12-53**, 19____, (Cross out incorrect words)

and approval of the proposed plan (was) (~~was~~) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Perforated 5-1/2" casing 6094-6135' with 4 jet shots per foot, total of 164 shots.

Witnessed by **P. E. Tally** **Humble Oil & Refining Co.** **Farm Boss**
(Name) (Company) (Title)

Approved: **OIL CONSERVATION COMMISSION**

S. J. Stanley
(Name)

Engineer District I

(Title)

AUG 24 1953

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name **M. M. Rogers**

Position **District Superintendent**

Representing **Humble Oil & Refining Co.**

Address **Box 2347, Hobbs, N. M.**

mcB/mcb

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100