State of New Mexico rgy, Minerals & Natural Resources Department

District I PO Box 1980, Hobbs, NM 88241-1980 District II 811 S. 1st Street, Artesia, NM 88210-2834 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV PO Box 2088, Santa Fe, NM 87504-2088

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, NM 87504-2088

Form C-101 Revised February 10, 1994 Instructions on back Submit to Appropriate District Office State Lease - 6 Copies Fee Lease - 5 Copies

AMENDED REPORT

APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

¹ Operator name and Address										² OGRID Number			
Marathon Oil Company										014021			
P.O. Box 2409										³ API Number			
Hobbs, NM 88240									30-0	30-0 25-10252			
4 Pro	perty Code			⁵ Property Name								Well Number	
	6377			Edith Butler "B"								1	
					⁷ Surface Location								
UL or lot no.	Section	Township	Range	ge Lot. Idn Feet		Feet from the No		outh Line	Feet from the	East/West line		County	
I 13 22-S		<u>37-E</u>		198		South		660	East		Lea		
⁸ Proposed Bottom Hole Location If Different From Surface													
UL or lot no. Section Township		Range	Lot. Idn	Feet from the		North/South Line		Feet from the	East/West line		County		
9 Proposed			Pool 1			<u>,l</u>	10 Proj		¹⁰ Proposed P	Pool 2			
Blinebry Oil & Gas													
11 Work Type Code 12			Well Type C	ode	13 Cable/Rotary			¹⁴ Lease Type Code		¹⁵ Ground Level Elevation			
			06		NA			Р		3326'			
16 Mul	A Itiple		17 Proposed De	pth	¹⁸ Formations			19 (¹⁹ Contractor		20 Spud Date		
					Blineb		-¥			1/22/96		00.00	
	No		6950'	²¹ Urono	sed Casing	ikard and Co	ment	Program	<u>NA</u>			22/96	
	<u> </u>		sing Size		weight/foot	· · · · · · · · · · · · · · · · · · ·	ting De		Sacks of Ceme	at		timated TOC	
See Orig	ginal	C	-105	[
								·· ,					
	······································												
²² Describe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary Marathon Oil Company is proposing to recomplete to the Blinebry formation in this well. Attached is a													
1 1						ne Di I	lebry	TUrillat		Well. A	ιιαι	ineu is a	
'			Administer F	rom A	pprovs,								
Permit Expires 6 Months From Approval Permit Expires 6 Months From Approval													
	12 Una	, ,,	<u> </u>		e suot tue communication								
Date Unless Drating Underway.													
²³ I hereby certify that the information given above is true and complete to the best of my knowledge and belief.						OIL CONSERVATION DIVISION							
Signature: Trad 9.00.						Approved by:							
Printed name: Rick Gaddis							Title: SEXTON						
Title: Advanced Production Engineer						Approval Data 1 9 1995 Expiration Date:							
Date:			Phone:			Conditions of Approval:							
1/08/95			(50	5) 393-7	7106 ext	Attached							

Form C-101 Section 22 Edith Butler B Well No. 1

- 1. MIRU PU. Kill well with 2% KCL water as needed. ND wellhead and NU hydraulic BOPE. POOH with tubing.
- 2. Utilize packer and RBP to test BOPE to 1500 psi.
- 3. PU and RIH with 5 ½" RBP and packer. Set RBP at ±5950'. Pull up packer to ±5940' and set. Test 5 ½" casing and RBP to 1000 psi. Unset packer and retrieve RBP, POOH with tools.
- 4. RU wireline company and lubricator. Perforate Blinebry Formation 2 JSPF at 5765-80', 5784-88', 5792-96', 5808-26' and 5830-40' for a total of 112 holes. RD wireline company.
- 5. PU and RIH with 5 ½"" treating packer, seating nipple to ±5700'. Test tubing to 4500 psi. Set packer at ±5700'.
- 6. Acidize Blinebry perforations 5765-5840' with 3,000 gals of 15% NEFE acid using ball sealers for divert.
- 7. Release packer and RIH to 5850' and PUH to 5700' and set. RU swab and recover acid load. Release packer and POOH with tubing and packer.
- 8. RU wireline company and lubricator. Perforate Blinebry Formation with 2 JSPF at 5482-92', 5496-5504', 5518-22', 5560-65', 5578-82', 5584-88', 5592-94', 5598-5608', 5610-32', 5648-54', 5662-88', 5700-08' and 5712-18' for a total of 256 holes. RD wireline company.
- 9. PU and RIH with 5 ½" RBP and treating packer. Set RBP at ±5750' and packer at 5740'. Test casing and RBP to 1000 psi. Release packer and PUH to ±5430' and set.
- 10. Acidize Blinebry perforations 5482-5718' with 6400 gals of 15% NEFE acid using ball sealers for divert.
- 11. Release packer and RIH to ±5725', PUH to 5430' and set. RU swab and recover acid load. RD swab and release packer and retrieve RBP. POOH with tubing and tools.
- 12. RU hydrotesters. PU 3 ½" workstring with seating nipple and 5 ½" treating packer and RIH to ±5430' and set.
- 13. RU stimulation company. Install frac valve and treating lines. Sand fracture Blinebry perforations 5482-5830' with CO_2 Size of fracture treatment will be determined after acidizing.

Form C-101 Section 22 Edith Butler B Well No. 1 Page 2

- 14. Flow well back to recover load. If well dies, RU slickline company and tag for sand fill.
- 15. If sand fill covers perfs, RU to remove with bulldog bailer.
- 16. Release packer and POOH laying down 3 ¹/₂" workstring and packer.
- 17. RIH with mud joint, seating nipple, TAC on 2 3/8" production string. Land seating nipple at ±5800' with TAC at ±5430'.
- 18. ND BOPE and NU wellhead.
- 19. RIH with insert pump on 3/4" and 7/8" rod string. Beam well, load and test.
- 20. RDMO PU. Start well pumping to battery on test.

RDG/BUTLERB1/rdg

District I PO Box 1980, Hobbs, NM 88241-1980 District II 811 S. 1st Street, Artesia, NM 88210-2834 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV PO Box 2088, Santa Fe, NM 87504-2088

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, NM 87504-2088

Form C-102 Revised February 10, 1994 Instructions on back Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

¹ API Number				² Pool Code			³ Pool Name							
30-025-10252			72	724806660					Blinebry Oil & Gas					
⁴ Property Code			I			perty Na	6 Well Number			Well Number				
6377			Edith	1			1							
7 OGRID No.					8 Op	erator Na	9 Elevation			Elevation				
01402	n Oil Co	Oil Company							GL: 3326'					
¹⁰ Surface Location														
UL or lot no.	Section	Township	Range	Lot. Id	In Feet fro	m the	North/South Line	Feet from the	East/West	t line	County			
I	13	22-S	37-E		19	980	South	660	East	;	Lea			
¹¹ Bottom Hole Location If Different From Surface														
UL or lot no.	Section	Township	Fownship Range		Lot. Idn Feet fr		North/South Line	Feet from the East/W		est line County				
				ĺ										
¹² Dedicated Acres	5 13 Joint	or Infill 14C	Consolidation	n Code	15 Order No.				•					
80	Y	NA				NA								
NO ALLOW	ABLE W	/ILL BE AS	SIGNED	TO TH	IS COMPLE	TION U	JNTIL ALL INT	ERESTS HAV	E BEEN (CON	SOLIDATED			
NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NONSTANDARD UNIT HAS BEEN APPROVED BY THE DIVISION														
_			<u> </u>				17	¹⁷ OPERA	FOR CER	RTIFI	CATION			
							U U				n contained herein is knowledge and belief .			
								thich Dodi						
								Signature						
								Rick Gaddi	S					
								Printed Name	roductic	on Er	ainean			
								Advanced P	roductin		igmeen			
			1X	`////	1/////	1/1	11/1/1	Date						
									YOR CE	RTIF	ICATION			
								hereby certify th	at the well	locatio	n shown on this plat			
			1		2				field notes supervision,		ual surveys made by hat the same is true			
			1		•		•-660- 1	and correct to the best	of my belief.					
			1					F.						
			A					<u>See Origir</u>	al Plat	<u>. </u>				
			'A			· • • •		Date of Survey						
			1	///	/////			Signature and Scal of	Professional Su	rveyer:				
							` 0							
							8							
							-							
							1							
							4	Certificate Number						