NO. OF COPIES RE	EIVED								
DISTRIBUTI	ON		NEW	MEXICO OIL CONSER	VATION COMM	IS SION		rm C-101	_
SANTA FE	1							evised 1-1-6	
FILE							5	г	Type of Lease
U.S.G.S.								STATE	FEE X
LAND OFFICE							. 5	, State Oil	& Gan Leane No,
OPERATOR									
	····· • • • • • • • • • • • • • • • • •							11111	
AP	PLICATIO	N FOR PI	ERMIT TO	DRILL, DEEPEN, C	OR PLUG BAC	ĸ	<u> </u>		
1a. Type of Work							7	. Unit Agre	ement Name
				DEEPEN X		LUG B			
b. Type of Well				DEEPEN	F	LUG BI		. Farm or L	ease Name
OIL WELL	GAS WELL		HER	5	ZONE X	MULTI		Hugh	
2. Name of Operator		0,				6		, Well No.	
								~	
Gulf 011 (3. Address of Opera	tor	10n		· · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·		0, Field and	i Pool, or Wildcat
Box 670, 1 4. Location of Well							k	Prinka	rd
4. Location of wen	UNIT LETTE	R <u>B</u>	LOC	ATED <u>660</u> FE	ET FROM THE	orth	LINE	//////	
1000		Π	- •	14	22.0	27 1	. 8	//////	
AND 1980	FEET FROM			E OF SEC. 14 TV	VP. 22-5 RGE	37-1		2. County	m)///////// /
	illilli					/////	, //////	•	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<i>111111</i>	HHH	<i>HHHH</i>		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<i>++++</i> -	HHHH.	Lea	<i>/////////</i>
		///////				////		//////	
	711111	τηπ	///////		<u>TITTTTT</u>	7111	<u>TTTTTT</u>	777777	
					. Proposed Depth		A. Formation		20. Rotary or C.T.
					6365'		Drinkard		
21. Elevations (Shou	v whether DF,	RT, etc.)	21A. Kind	& Status Plug. Bond 21	B. Drilling Contro	dctor		22. Approx	. Date Work will start
3342' GL			Bla	nket	•			Decem	ber 1, 1973
23.			~						
-			P	ROPOSED CASING AND	CEMENT PROGR	AM			
SIZE OF H	IOLE	SIZEOF	CASING	WEIGHT PER FOOT	SETTING DE	РТН	SACKS OF	CEMENT	EST. TOP
17-1/4"		13-3	/8''	48#	309'		300 sa	ks (Ci	rculated)

SIZE OF HOLE	SIZE OF CASING	WEIGHT FER FOUT	SETTING DEFTH	JACKS OF CEMENT	E31. TUP
17-1/4"	13-3/8"	48#	309'	300 sacks (Ci	rculated)
12-1/4"	9-5/8"	36#	2861'	1300 sacks (TO	C at 1475').
8-3/4	Ζ''	23#	6397'	600 sacks (TO	

Plans have been made to abandon the Paddock zone and complete in Drinkard as follows:
Pull producing equipment. Squeeze Paddock perforations 5100' to 5200' with 250 sacks
of Class C cement. WOC 24 hours. Clean out to 6365'. Test squeezed perforations with 500#,
30 minutes. Perforate Drinkard zone in 7" casing with 2, .72" JHPF at approximately 6240' to
6320'. Run treating equipment. Treat new perforations with 1200 gallons of 15% NE acid and
20,000 gallons of gel brine water. Flush with 1500 gallons of gel water. Pull treating equipment. Run 2-3/8" tubing and packer. Set packer at approximately 6175'. Swab and clean

up and return well to production.

hereby certify that the information	above is true and complete	to the best of my knowledge and belief.		
igned H. J. Are	alale_ Til	le Area Engineer	Date November 28	, 1973
(This space for Sta	ye Use)	<u> </u>		

CONDITIONS OF APPROVAL, IF ANY: