

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dual</b>		7. Unit Agreement Name
2. Name of Operator <b>Amerada Hess Corporation</b>		8. Farm or Lease Name <b>E. W. Walden</b>
3. Address of Operator <b>Drawer "D" - Monument, New Mexico 88265</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>K</b> , <b>2009</b> FEET FROM THE <b>South</b> LINE AND <b>1911</b> FEET FROM THE <b>West</b> LINE, SECTION <b>15</b> TOWNSHIP <b>22S</b> RANGE <b>37E.</b> NMPM.		10. Field and Pool, or Wildcat <b>Blinebry/Drinkard</b>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set wireline plug in on and off tool in Drinkard Zone. Killed Blinebry zone with treated water. Pulled 2-3/8" tbg., and ran dual strings of tbg. with parallel anchor. pulled wireline plug, swab back Blinebry through short string and Drinkard through long string and placed both zones back to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Porter TITLE Admin. Serv. Supv. DATE 8/30/76

APPROVED BY Jerry Sexton TITLE Dist. 1. Supv. DATE SEP 7 1976

CONDITIONS OF APPROVAL, IF ANY: