

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Comingled</u>		7. Unit Agreement Name
2. Name of Operator <u>Amerada Hess Corporation</u>		8. Farm or Lease Name <u>E. W. Walden</u>
3. Address of Operator <u>Drawer D, Monument, New Mexico 88265</u>		9. Well No. <u>7</u>
4. Location of Well UNIT LETTER <u>N</u> <u>754</u> FEET FROM THE <u>South</u> LINE AND <u>1957</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>Blinebry - Drinkard</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3387' GR</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Down hole comingled</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull tbq., run drlq. bailer & drill cement & knock Model D pkr. loose at 6397' and push to 6470', re-opening Drinkard zone csg. perfs. 6435' to 6470'. Run tbq., pump & rods and resume production down hole comingled in Drinkard and Blinebry zones as approved by administrative order DNC-452, 2-6-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. B. Sinner TITLE Supv. Adm. Ser. DATE 3-29-84

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE

APR 3 1984

MAR 30 1984
G.C.D.
HOLDS OFFICE