

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions
verse side)

5*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N.M. 0557256

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR ANADARKO PRODUCTION COMPANY		8. FARM OR LEASE NAME Elliott Federal	
3. ADDRESS OF OPERATOR P. O. Box 806, Eunice, New Mexico 88231		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEL		10. FIELD AND POOL, OR WILDCAT Penrose-Skelly	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) N/A	
		12. COUNTY OR PARISH Lea	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. RUPU;
2. Ran 2-3/8" tbg. to 3680', 08/16/76;
3. Cmt. shot hole w/150 sks of Halliburton Light w/1/4# Flocele & 2% Calc. chl. per sk., 08/17/76;
4. Tagged top cmt. @ 2717', 08/18/76;
5. Loaded hole w/salt gel mud;
6. Spotted 25 sk. plug @ 2600', 1200', 500', & surface, 08/18/76;
7. Installed dry hole marker, 08/19/76;
8. RDPU;
9. Removed anchors & leveled location.
10. Location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED Chris Henderson


TITLE Area Supervisor

DATE 08/19/76

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____



*See Instructions on Reverse Side

RECEIVED

SEP 2 1977

OIL CONSERVATION COMM.
HOBBS, N. M.

GENERAL