## NEW ME O OIL CONSERVATION COMP 'SION Form C-110 SANTA FE, NEW MEXICO Revised 7/1/55

(File the original and 4 copies with the appropriate district office)

## CERTIFICATE OF COMPLIANCE AND AUTHORIZATION TO TRANSPORT OIL AND NATURAL GAS

Company	or Oper	ator Texas Pa	cifi.	c Coal	۵ 0 <u>11</u> 0	ompany	Le	ase F1	liett B−	15
Well No	1	Unit Letter	<u> </u>	S 15	T 22	R_37	Pool	Drinks	ırd	
County	Lea		Kind	of Le	ase (Sta	ate, Fed	. or Pa	tented)	Federa]	L
If well pro	oduces c	oil or condens	ate,	give lo	ocation	of tanks	:Unit B	S 15	T 22	R 37
Authorize	d Trans	porter of Oil	or C	ondens	ate	Shell H	peline	Corporat	ien	
Address_		address to w								
A - 41	(Give	address to w	hich	approv	ved cop	y of this	form i	s to be	sent)	
Authorized	1 Trans	porter of Gas			Skelly	Oil Comp	eny EF	FECTIVE	JANUATY	31, 1977.
Address	1 Cirro	address to w	<del></del> -		Tulsa	Oklahoma	SK	ELLY OIL	COMP	Y MERGE
lf Gas is n	not being	g sold, give r	easo	ns and	also ex	xplain its	prese	nt dispo	sition:	
Reasons for Change in	Transpo	g:(Please checorter of (Checo	k On	e): Oil	l ( ) D	ry Gas	( ) C'h			
Remarks:					(x) Ot	her	Cive e	vnla nati.	on h -1	()
The unders	Coal &	hip changed fr Oil Company a	om R	owan Oi Ju <b>ly</b> 1	1 Compa , 195%.	A DIVIDIO.	CHANGE OF TEXAS PACIFIC OF JOSEPH TEXAS PACIFIC	OPERATION FE TO GUL OCTION F. CHARLET	0M SY 4 90MS, 1 2,	
	· o seem	ertifies that the complied with	11.				o <del>t the</del> O	il Conse	rvation	Com-
Executed th	nis the_	11 day of		July	1955	<del></del>				
Approved_				19		By	histrict	A. A.	<u>len</u>	
OIL (	CONSER	VATION COM	1MIS:	SION		Company				7 C-
Ву	andres a gari	The second secon								L UU
		<del></del>		<del></del>	P	ddress_	P. O. B	ox 16 <b>8</b> %	<del></del>	
Title		4		<del></del>			Hebbs,	New Mexi	G <b>o</b>	

## SCOUT REPORT NEW MEXICO

		1	,		OIL	CONSERVAT	ION CO	MMISSI	ON				
			<u> </u>			Company	Rowan	Dril lin	g Compan	Ŋ			
			_	<b>&gt;</b> -		Farm Name		iott B-1		-	ell No.	1	
						Land Classifi		Govern	_				
			- -			Sec. 15	Twp.	22	Range	37	Cour	<sup>ıty</sup> Lea	-
≱					— т	Feet from Li	ne: 660		s	•	Ε.		w.
						Elevation					Method	l	
			_			Contractor						Scout	
						Spudded		Completed	l	Initia	al Produ	action	,
						Bond Status				·			
			s		ACID	RECORD			1	TA			
	Casin	Amor g and Cem		Record		Gals,			-	TS			
	Size	Feet	Inches	Sax Cement		dais,		<del></del>		BS			
				Centent						TRS			
		_		-						TBL			
					Top P	ay	·	TD		TWL			
	-	Tubing I	Record					SHOOTIN	G RECOR	D		<del></del>	
					No. of	Quarts		Shot	at		F	eet	
		<del> </del>			No. of	Quarts		Shot	at		F	eet	
					<u>\$/0</u>		S	/0		S/	0		
					<u>S/0</u>		S	/0		S/	0		
DA	TE	8 <b>-</b> 7 <b>-</b> 40					DATE	<del></del>					
<b>\U</b> G	14												
		1											
			· · · · · · · · · · · · · · · · · · ·		<del></del>								
				<del></del> -				-					
												-	

Depth	Formation	Depth	Formation	Depth	Formation
-				·	
				-	
		ļ			
				i	
		1			
		1			
		1			