Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 Example 2 State of New Mexico Example 2 State of New Mexico

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL LOCATION AND ACREAGE DEDICATION PLAT

All Distances must be from the outer boundaries of the section

perator				Lease					Well No.	
Zia Fne	rgv. Tr	nc.		Cole	Stat	te			1	
	tion	Township		Range				County	· · · · · · · · · · · · · · · · · · ·	
A	16	22 So	outh		East	N	MPM		Lea	
ctual Footage Location	of Well:				(())			17.00	+	
	t from the	North	line and		660	feet	from	he Eas	L line Dedicated Acrea	
ound level Elev.	}	ing Formation		Pool			~			-
3405'	S	an Andres				Funice	Sai	n Andre	s 40	Acres
2. If more that 3. If more that	n one lease is d	ted to the subject well redicated to the well, o different ownership is etc.?	outline each and dedicated to the	l identify the ow e well, have the	vnership the interest of	creof (both as to				
If answer is "r this form if ne	s [o" list the own	No If and tract description	ions which have		consolidated					
No allowable or until a non-	will be assigne standard unit,	d to the well until all eliminating such inter	interests have b est, has been ap	een consolidate proved by the I	d (by comn Division.	nunitization, unit	ization	, forced-poolin	ig, or otherwise)	
						99 -660_	b	I hereby ontained here est of my know signature Jacob Trinted Name	COR CERTIFIC certify that th in in true and c whedge and belief.	e informatio
								osition Engine Company Zia Fr Date 1/18/0	nergy, Ir	nc .
	 							l hereby certi on this plat actual survey supervison, a	YOR CERTIFI fy that the well was plotted from s made by me nd that the sam we best of my	location sho field notes or under se is true a
					 			Date Surveyed Signature & S Professional S	ieal of Surveyor	
]							Certificate No		
0 330 660 99	0 1320 16	50 1980 2310 2	2640 2	2000 1500	1000	500	o			

Submit 3 Copies to Appropriate Energy, District Office	State of New Mexico nerals and Natural Resources Department	Form C-103 Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240	CONSERVATION DIVISION P.O. Box 2088	WELL API NO. 30-025-10321
DISTRICT II Sa P.O. Drawer DD, Artesia, NM 88210	nta Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. B = 3480
SUNDRY NOTICES AND	PEPOPTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE (FORM C-101) FOR S	O DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
I. Type of Well: OIL GAS WELL X WELL	OTHER	Cole State
2. Name of Operator		8. Well No.
Zia Energy, Inc.		9. Pool name or Wildcat
P.O. Box 2219, Hobbs,	NM 88241	Southwest Eunice San Ar
	3405' GR ate Box to Indicate Nature of Notice, F N TO: SUB G AND ABANDON REMEDIAL WORK NGE PLANS COMMENCE DRILLIN	BSEQUENT REPORT OF:
PULL OR ALTER CASING		
OTHER:		
		u to San Andres
 12 Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103. 1. Rigged up Clarke Well 2. Rigged up reverse ci consisting of 6 1/8" 3. Commenced cleaning of 4. Ran 5" - 13# liner f Hanger. Cemented us 5. Tested liner top to 6. Ran GR - CNI, from 39 3778' to 3914'. 	y state all periment details, and give pertiment dates, incl rculation equipment. Pic bit, 12 - 4 3/4" DC and out @ 3685' and drilled all rom 3984' up to 3499'. H sing 75 s x s cement. 500# - ok. 984" to 2000'. Perforated	Wing estimated date of starting any proposed tubing, rods, and pump. eked up the work string 2 7/8" tubing. nead to 3984'. Hung liner on Baker Liner 1 14 - 1/2" holes from
 12 Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103. 1. Rigged up Clarke Wel 2. Rigged up reverse ciconsisting of 6 1/8" 3. Commenced cleaning of 4. Ran 5" - 13# liner f Hanger. Cemented us 5. Tested liner top to 6. Ran GR - CNI, from 39 3778' to 3014'. 7. Acidized using 1000 8. Ran 2 3/8" tubing, r production. 	y state all pertinent details, and give pertinent dates, incl I Service. Pulled 2 3/8" rculation equipment. Pic bit, 12 - 4 3/4" DC and out @ 3685' and drilled all from 3984' up to 3499'. H sing 75 s x s cement. 500# - ok. 984" to 2000'. Perforated GA. rods, and 2" X 1 3/4" X 16	Weing estimated date of starting any proposed tubing, rods, and pump. Eked up the work string 2 7/8" tubing. Thead to 3984'. Mung liner on Baker Liner 1 14 - 1/2" holes from 6' pump. Placed well on
 12 Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103. 1. Rigged up Clarke Wel 2. Rigged up reverse ci consisting of 6 1/8" 3. Commenced cleaning of 4. Ran 5" - 13# liner f Hanger. Cemented us 5. Tested liner top to 6. Ran GR - CNI, from 39 3778' to 3914'. 7. Acidized using 1000 8. Ran 2 3/8" tubing, r production. 	y state all periment details, and give pertiment dates, incl I Service. Pulled 2 3/8" reculation equipment. Pic bit, 12 - 4 3/4" DC and out @ 3685' and drilled and 'rom 3984' up to 3499'. H sing 75 s x s cement. 500# - ok. 984" to 2000'. Perforated GA. rods, and 2" X 1 3/4" X 16 e to the best of my knowledge and belief.	Weing estimated date of starting any proposed tubing, rods, and pump. Eked up the work string 2 7/8" tubing. Nead to 3984'. Mung liner on Baker Liner 1 14 - 1/2" holes from 6' pump. Placed well on
 12 Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103. 1. Rigged up Clarke Wel 2. Rigged up reverse ciconsisting of 6 1/8" 3. Commenced cleaning of 4. Ran 5" - 13# liner f Hanger. Cemented us 5. Tested liner top to 6. Ran GR - CNI, from 39 3778' to 3014'. 7. Acidized using 1000 8. Ran 2 3/8" tubing, r production. 	y state all pertinent details, and give pertinent dates, incl I Service. Pulled 2 3/8" Proulation equipment. Pick bit, 12 - 4 3/4" DC and put @ 3685' and drilled all from 3984' up to 3499'. H sing 75 s x s cement. 500# - ok. 984" to 2000'. Perforated GA. rods, and 2" X 1 3/4" X 16 e to the best of my knowledge and belief. Second Second Second Second DRIGINAL SIGN	Weing estimated date of starting any proposed tubing, rods, and pump. Eked up the work string 2 7/8" tubing. nead to 3984'. Jung liner on Baker Liner 1 14 - 1/2" holes from 6' pump. Placed well on <u>c</u>
 12 Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103. 1. Rigged up Clarke Wel 2. Rigged up reverse ci consisting of 6 1/8" 3. Commenced cleaning of 4. Ran 5" - 13# liner f Hanger. Cemented us 5. Tested liner top to 6. Ran GR - CNI, from 39 3778' to 3014'. 7. Acidized using 1000 8. Ran 2 3/8" tubing, r production. 	y state all pertinent details, and give pertinent dates, incl I Service. Pulled 2 3/8" Proulation equipment. Pick bit, 12 - 4 3/4" DC and put @ 3685' and drilled all from 3984' up to 3499'. H sing 75 s x s cement. 500# - ok. 984" to 2000'. Perforated GA. rods, and 2" X 1 3/4" X 16 e to the best of my knowledge and belief. Second Second Second Second DRIGINAL SIGN	Weing estimated date of starting any proposed tubing, rods, and pump. Eked up the work string 2 7/8" tubing. head to 3984'. Jung liner on Baker Liner 4 14 - 1/2" holes from 6' pump. Placed well on <u>c</u>