

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	5 1/2"	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION TO PLUG WELL
NOTICE OF INTENTION TO DEEPEN WELL		

Hobbs, New Mexico February 13, 1939.

Place

Date

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intention to do certain work as described below at the

DUPLICATE


GULF OIL CORPORATION      Cole State "B"      Well No. #4      in C SW/4 NW/4  
 GYPSY DIVISION      Lease  
 Company or Operator  
 of Sec. 16      T. WW 1/1      R. 37      N. M. P. M.,      Penrose      Field,  
 Lea      County.

## FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Feb 12, 1939 the 5 1/2" OD 20# 10thd New SS Casing was cemented in Lime at 3521' with 225 sacks by the Halliburton Cementing process.

Propose to drill plug and test at 630 AM February 14, 1939.



Approved FEB 14 1939, 19  
 except as follows:

OIL CONSERVATION COMMISSION,  
 By R. O. Yarkhroff  
 Title OIL & GAS INSPECTOR

GULF OIL CORPORATION  
 GYPSY DIVISION  
 Company or Operator  
 By C. C. Cummings  
 Position District Supt.  
 Send communications regarding well to  
 Name C. C. Cummings,  
 Address Hobbs, New Mexico.