

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP  
(Other instructions  
verse side)

TE-  
re-

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC - 032573-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Elliott B-17

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Penrose Skelly - GB

11. SEC., T., R., M., OR BLM. AND  
SURVEY OR AREA

Sec 17, T22S, R37E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL ☒ GAS ☐ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR ARCO OIL & GAS COMPANY

Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P.O. Box 1710 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit A, 660' FNL & 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3403' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Casing Test

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

X

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

TD 3700'

5-17-88 MIRU, test anchor. Start out w/rods, dropped rods. Fished rods & POH  
laying down. ND wellhead, NU BOP, POH w/tubing. SION

5-18-88 RIH w/baker lock set packer to 3497', set packer, load casing ~~to~~ press  
to 650# & held for 15 min.

Witnessed by Jack Johnson w/ BLM

POH w/packer & lay tubing down. ND BOP, NU wellhead.  
Rig down.

CHART ATTACHED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Services Supv.

DATE 5-19-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JUL 21 1988

Peter M. Christie  
CARLSBAD, NEW MEXICO

\*See Instructions on Reverse Side