Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OIL	CONSERVAT	TON DIVISION	ON			
		P.O. Box					
DISTRICT I		Santa Fe, New	Mexico 8750	4-2088			
P.O. Box 1980, Hobbs, NM 8	8240						
DISTRICT II					API NO. (sesigned by OCD on New Wells) 30-025-10359		
P.O. Drawer Dd, Artesia, NM	88210						
DISTRICT III  1000 Rio Brazos Rd., Aztec, I	Nm 87410				5. Indicate Type	STATE	FEEX
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						<u> </u>	
					6. State Oil & G	as Lease No.	
r	CUMPRY MOTICES	AND DEDOOTS	ONIWELLS				
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					7. Lesse Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					ARROWHEAD GRAYBURG UNIT		
		R SUCH PROPOSALS.			7		•
1. Type of Well:					7		
OIL	GAS						
WELL X	WELL	OTHER					
2. Name of Operator	NA 14 0 A 1810				8. Well No.	245	
	N U.S.A. INC.	•			9. Pool name or \	245	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON					ARROWHEAD GRAYBURG UNIT		
4. Well Location	3.5.4.5, 1.7.7.5.			······································	<del> </del>		
Unit Letter	::	660 Feet From The	NORT	H Line and			AST Line
Section	19		22S how whether DF, RKB,	Range	37E	NMPM LEA	County
		70. Elevation(Si	3410'	, , , , , , , , , , , , , , , , , , ,			
11	Check Appropriate	Box to Indecate Natur		or Other Data	· · · · · · · · · · · · · · · · · · ·		
	OF INTENTION TO:	box to inaccate itata		SEQUENT RE	PORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	,	REMEDIAL WORK	Г	7	ALTER CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS.	7	PLUG AND ABAN.	
PULL OR ALTER CASING		<u> </u>	CASING TEST AND CM	<del> </del>	4		
OTHER:			OTHER: C/O, A	<u>.                                    </u>			X
OTHER.			<u> </u>				12.
12. Describe Proposed or Co	ompleted Operations(Clearly state al	pertinent details, and give	e pertinent dates, includ	ing			<del></del>
esticated date of starting	any proposed work) SEE RULE 110	3.					
	J 12/19/95. TAG TD. P						
ACD:	Z 3584'-3704' AND 37	14'-3813' WITH	3000 GALS AC	ID.			
	N/2 7/8" TBG TO 3801		( )				
TURI	N WELL OVER TO PROD	UCTION 12/22/9	<b>15.</b> $\%$				
I hereby certify that the inform	nation above is true and complete t	the best of my knowledg	ge and belief.				
SIGNITURE TO	nd X Anaston	TITLE	TECH. ASSIST.	ANT	DATE:	1/23/96	
	10					/04E1007.7000	
TYPE OR PRINT NAME	WENDI KINGST	ON			TELEPHONE NO.	(915)687-7826	
	OPIGMAL SIGNE	D BY				JAN 26	1996
APPROVED BY	DATE MINK				DATE	3711 20	
CONDITIONS OF APPROVAL		7					