Santa, Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL.
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL
NOTICE OF INTENTION TO DEEPEN WELL	
	Wink, Texas August 15,1938.
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen:	DUPLICATE
Following is a notice of intention to do certain wo	ork as described below at the
The Texas Company-Parker Drlg  Company or Operator  Lease	Co. State "A" Well No. 1 in SW1-SW1
of Sec. 21 T. 22 S., R. 37	E., N. M. P. M., Penrose Area Field,
Lea County.	- PROPOSED DI AN OE WORK
FULL DETAILS C FOLLOW INSTRUCTIONS IN THE	F PROPOSED PLAN OF WORK RULES AND REGULATIONS OF THE COMMISSION
Total depth -1147' Anh	ydrite.
with 100 sacks of Trinity Specific 5:00 PM. 8-11-38.  Anticipate drilling place	of 8-5/8"OD, 32#, lapweld casing at 1147' ecial cement. Completed cementing at ug and testing casing after 72 hours or
at approximately 5:00 PM. 8-1 method.	4-39. Casing will be tested by bailing  AUG 191938
	HOBBS OFFICE
AUG 1 € 1938	OFFICE
Annroyad	The Texas Company.  Company or Operator
except as follows:	Company or Operator
	By I H Shiple Town
•	0.20, 94
	Position District Superintendent Send communications regarding well to
OIL CONSERVATION COMMISSION,	Name The Texas Company
By Rose Walke R. )	U. Address Drawer K, Wink, Texas.
Title Title Gas Inspector	