XXXXXXXXXXXXXXXXXXXXXXXXX

Box 522 Carlsbad, New Mexico April 11, 1936

Mr. Loyd Lamb Tide Mater Oil Company Box KX Hobbs, New Mexico

Dear Mr. Lamb:

I am returning herewith form C-101, "Notice of Intention to Drill" your R. L. Bronson Well #1 in the SE2 of Sec. 21, T. 22 S., R. 37 E., for correction.

The casing program for this area is as follows: The surface pipe shall be set at least 15 feet into the red beds and cemented to the surface. The production string of casing shall be set either on the top or within the producing zone. Where no intermediate string is used the production string shall be cemented with 150% of the calculated amount required to fill back to bottom of cellar. Or a two-stage cement job may be used, the lower stage shall be cemented with at least that amount of cement which would theoretically bring the cement 200 feet above the casing shoe. The upper stage shall cement the string from just below the top of the salt to the surface, using 150% of the calculated amount.

With kindest regards. I am

Very truly yours,

FJV:t

F. J. Vesely, State Oil & Gas Inspector.

Encls.