		Form C-103 Supersedes Old
	7 · · · · · · · · · · · · · · · · · · ·	Pera
NO. OF COPIES RECEIVED	<u> </u>	Form Callon
DISTRIBUTION	\downarrow	Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	C•102 and C-103
FILE		Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		
OPERATOR		5. State Oil & Gas Lease No.
CHAID	DV NOTICES AND DEPOSIT	at the off a day bedge 140.
100 NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -'' (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER- Water Injection Well	7. Unit Agreement Name Langlie Mattix Penros
2. Name of Operator		Skafiv Unit 8. Farm or Lease Name
Anadarko Productio 3. Address of Operator	n Company	Tr 5A
		9. Well No.
	dunice, New Mexico 88231	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTERD	660 FEET FROM THE North LINE AND 660 FEET FROM	Langlie Mattix
	on 22 township 22S range 37E nmpm.	
	15. Elevation (Show whether DF, RT, GR, etc.)	
	3372' GR	12. County
16. Chark		Lea
NOTICE OF IN	Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data
	SOBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON		ALTERING CASING
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CASING TEST AND CEMENT JOB	
OTHER	OTHER	
 Describe Proposed or Completed Opwork) SEE RULE 1103. 	perations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
well SA-1 on form (C-120 is shown to be SI 12-76. Request permissi	on to TA well
until we can get of	k & AFE for workover & perform remidial work. C	ement lined
tubing & packer st	ill in tact. Well is SI.	

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Levelle Section

Orig. Signed by

Detty Sexton

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Expression

Expression

OCT 15 1979

CONDITIONS OF APPROVAL, IF ANY: