

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
LC-
77-032573A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Arch Petroleum Inc.	8. FARM OR LEASE NAME E.M. Elliott Federal
3. ADDRESS OF OPERATOR 777 Taylor St., Suite II-A, Ft. Worth, Texas 76102	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit C, 510 FNL & 2130 FWL, Section 22, T-22-S, R-37-E	10. FIELD AND POOL, OR WILDCAT Tubb
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA Sec 22, T-22-S, R-37-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3386 GR	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Plug back Tubb

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Purpose to plug back the Tubb formation perforated at 5964-6142' by setting a CIBP in the 7" casing at 5925' with 35' cement on top.

Purpose to recomple in Blinebry formation by perforating intervals between 5420-5700'.

Purpose to acidize and fracture zones as necessary to test for oil and gas production.

Purpose to begin work upon approval.

RECEIVED
JUN 13 11 24 AM '89
OFFICE OF THE ATTORNEY GENERAL

18. I hereby certify that the foregoing is true and correct

SIGNED

David Miller

TITLE David Miller

DATE 6-13-89

(This space for Federal or State office use)

APPROVED BY

James J. Smith

For:

TITLE OFFICE MANAGER

DATE 6-27-89

CONDITIONS OF APPROVAL, IF ANY

*See Instructions on Reverse Side

RECEIVED

JUN 28 1989

**OCD
HOBBS OFFICE**