	10 A. 41		2 -		<b>م</b> ر م	<u> </u>		
Fo	m	n (	]-:	10	B-~	3		
		• 2	5 <b>- 4</b> -		: چنری		L	,

## **OIL CONSERVATION COMMISSION**

Santa Fe, New Mexico

U)

REPORTS

on wells



Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten to be the specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission. Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERA- TIONS	REPORT ON REPAIRING WELL	X
REPORT ON RESULT OF SHOOTING OR CHEM- ICAL TREATMENT OF WELL	REFORT ON PULLING OR OTHERWIS ALTERING CASING	E
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		·
		d, Texas
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO Gentlemen:	Dave	•
	ults obtained under the heading noted above at the	
Company or Operator	· Lease	
<u>NE/4 of SE/4</u> of Sec	<u>22</u> , T. <u>22-S</u> , R. <u>37-E</u>	_, N. M. P. M.,
Brunson Field,	Lea	County.
The dates of this work were as follows:	October 26, 1949 to December 6, 194	9
Notice of intention to do the work was (War work	submitted on Form C-102 on October 4	19_49
and approval of the proposed plan was (Was Gat)		
	WORK DONE AND RESULTS OBTAINED	

See Reverse side.

Name	Company	Title
	<pre>is true and correct Name Position Division Chief Cl Representing Humble Oil &amp; R</pre>	edfacts erk efining Company
6-1-51	Address Box 1600, Midland,	Texas
	<u> </u>	Title
	e me this mber1949 Notary Public 6-1-51	Image: Second state     Image: Second state       Imag

Deepened well from original total depth of 7940' to 7965'. Set packer at 7946' and swabbed 2 hours. Packer failed. Drilled to 7975'. Set packer at 7757' with 210' of tail pipe. Swebbed well 24 hours. On 5 hour test, made 3 bbls. fluid per hour, 75% water. Drilled to 7984' and swabbed 75% water. Spotted 20 sacks cement on bottom and plugged back to 7900'. Could not set packer. Spotted 15 sacks cement from 7900' to 7897'. Spotted 15 sacks to 7876'. Set packer at 7799'. Swabbed 20 hours, 2.5 bbls. water per hour. Swabbed 9 hours at rate of 2 bbls. per hour, 90% water. Spotted 15 macks cament back to 7856'. Set packer at 7773'. Treated from 7830' to 7856' with 500 gals. mud acid. Swabbed 5 bbls. salt water per hour for 112 hrs. Cemented with 50 sacks cement through perforations from 7856' to 7830'. Drilled out coment to 7848'. Perforated casing from 7830' to 7845'. Swabbed well dry after 9 hours. Treated from 7830' to 7845' with 500 gals. LT acid. Swebbed well dry. Treated from 7830' to 7845' with 1000 gals. 15% LT acid. Swabbed 10 hours at rate of 6 bbls. fluid per hour, 95% water. Chloride content 62,000 PPN. Spotted 35 sacks cement from 6700\* to 6501". Ferforated casing from 6365" to 6405" and 6425" to 6445". Set packer at 6309". Swabbed well dry. Treated from 6365' to 6465' with 1000 gals. LT scid. Well flowed 157 bbls. fluid in 7 hours and died. Shut well in. Opened well on 1/4" choice and made 1 bbls. and died. Swabbed well 4 hours at rate of 5 bbls. fluid per hour, 2% BS and 4% water. Chloride content 147,000 PPM. Swabbed 8 hours at 2 bbls. fluid per hour, 3% BS and 3% water. Treated from 6365' to 6405' and 6425' to 6445' with 4000 gals. 15% LT acid. Formation took all acid and 25 bbls. water under vacuum. Swabbed well dry. Ran swab every hour for 8 hours and made no oil or gas. Spotted 45 sacks cement from 6501' to 6201' and 30 sacks from 5450! to 5249!. Perforated 52" casing from 5200! to 5230!. Swabbed fluidto 3000!, 100% water. Swabbed 12 hours at 8 bbls. fluid per hour, 995 water. Chloride content 127,000 PPM. Spotted 25 sacks cement from 5249' to 5105'. Perforated casing from 5056' to 5030'. Swabbed well to bottom. Ran swab each hour and recovered 1/2 bals. fluid, 95% water. Treated from 5056' to 5080' with 1000 galas LT acid. Swabbed fluid to 2500'. Swabbed fluid at rate of 6 bbls. fluid per hour, 100% salt water. Will plug and abandon well.

İ

Ì

all of the former and the