

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <b>Langlie Mattix</b>
2. Name of Operator <b>Anadarko Production Company</b>	8. Farm or Lease Name <b>Penrose Sand Unit</b>
3. Address of Operator <b>P. O. Box 247, Hobbs, New Mexico 88240</b>	9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>22</b> TOWNSHIP <b>22S</b> RANGE <b>37E</b> NMPM.	10. Field and Pool, or Wildcat <b>Langlie Mattix</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3352' GR</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up well servicing unit, pull tubing and rods.
2. Rig up reverse circulation equipment.
3. Clean out to total depth of 3686'.
4. Fracture treat, through 4½" treating string, below a packer set at approximately 3300'. Treatment to consist of 60,000 gallons of 9# gelled brine and 110,000# sand, using rock salt to stage treatment into four stages.
5. Remove treating string, rerun tubing and rods. Place well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. J. Ramey TITLE Area Supervisor DATE 9-21-72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE SEP 25 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 25 1972

OIL CONSERVATION COMM.  
RODERS, N. M.