

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.
30-025-10424

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

O.I. Boyd

8. Well No.

3

9. Pool name or Wildcat
Blindbry

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter O 660 feet from the South line and 1980 feet from the East line

Section 23 Township 22-S Range 37-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hrs prior to MI & RU.
2. Set 7" CIBP @ 5510', spot 20sx plug 5510'-5410'(Blindbry) WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25 # gel p/BBL.
4. Spot 60sx plug 2950'-2600'(9 5/8" shoe, B-salt, Yates) WOC Tag.
5. Spot 40sx plug 1400'-1200'(T-salt)
6. Perf 4 holes @ 375', sqz 75sx plug 375'-150'(13 3/8" shoe) WOC Tag.
7. 10sx surf, Install dry hole marker.

THIS COMPLETION WAS NOTIFIED 24
HOURS PRIOR TO THE START OF
PLUGGING OPERATIONS IN ACCORDANCE
TO BE APPROVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.R. Bledsoe TITLE HESS specialist DATE 9/30/2002

Type or print name G.R. Bledsoe Telephone No. 915.687.7153

(This space for State use)

APPROVED BY GARY W. WINK DATE OCT 05 2002

Conditions of approval, if any:

ORIGINAL SIGNED BY

GARY W. WINK

OFFICE FIELD REPRESENTATIVE / STAFF MANAGER