

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Case	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. <b>NMJ-528</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - <b>T.A.</b>	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL COMPANY</b>	8. Farm or Lease Name <b>Boyd</b>
3. Address of Operator <b>P.O. Box 1069 - Hobbs, New Mexico</b>	9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>B</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>23</b> TOWNSHIP <b>22-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Penrose Skelly</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3333' DF</b>	12. County <b>Lea</b>

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER **Temporarily Abandoned** ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pulled BP & tbq.
2. Ran open-end tbq. & pkr. @ 3588'. Plugged back w/frac sd. to 3670'.
3. Squeeze w/100 sks. incor + 6% halad 9 + 1% CA CL. Reversed out & pulled tbq. & pkr.
4. Acidized w/500 gal. acid across perms. 3510-80'. Pkr. @ 3455'.
5. SOT w/15,000 gal. lse. crude + 15,000# 20/40 sd. + 1/20# Adomite in 3 stages. Swab.
6. Ran 3530' 2" tbq., placed on pump.
7. No fluid in well. Remains temporarily Abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Heider Stang* TITLE Area Superintendent DATE 9-13-66

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: