

- 60,000# on 2-3/8 tbg. Would not come free. No movement. RIH w/1-11/16 chemical cutter and collar locator to 2863 (cut 2-3/8 tbg 15' about collar). POH J.C. 530 PU. POH w/2-3/8 tbg (90 jts lay down).
- 3-20 RIH w/4-11/16 overshot, bumper sub, jars, 6-3½" DC's, 2-7/8" tbg, tag and latch fish 2863'. Jar fish 3-½ hrs, made 17". Jars failed, POH w/2-7/8" tbg, 6-3½ DC's, jars, bumper sub, and 4-11/16 overshot.
- 3-22 RIH w/4-11/16 overshot on 2-7/8 tbg. Tag & latch fish 2863/McCullough WL Run 1-3/8 collar loc. & string shot did not show tbg. Parted @ 3123. Lower & shoot in tbg collar @ 3155. Indicated tbg parted after shot/RIH overshot POH/RIH w/ 4-11/16 overshot bumper sub jars 6-3½ DC, on 2-7/8 tbg. Tag & latch fish @ 2863/jar on fish 2 hrs w/no movement. Jars failed/RIH fish POH.
- 3-23 RIH w/4-11/16 overshot & fishing assy on 2-7/8 tbg/tag & latch fish 2863/(Pump 25 DCL down csg) jar on fish 5 hrs. Fish parted. POH rec 15' cut off jt & 15' piece 2-3/8 tbg w/heavy external corrosion leaving top of fish @ 2893/RIH w/4-3/4 impression block tag @ 2883 POH/Impression block indicated csg collapse to 3-3/4".
- 3-24 Corrected top of fish 2885/RIH w/3-7/8 swage 1 3-1/8 DC bumper sub jars 6-3½ DCs on 2-7/8 tbg. Tag & swage out csg 2883-85 in 20 min tag top of fish POH/RIH w/4-¼ csg swage bumper sub jars 6-3½ DC on 2-7/8 tbg/tag & swage 2883-85 in 10 min/POH/RIH w/3-5/8 impression block on 2-7/8 tbg. Tag @ 2883/POH imp. block indicated csg collapsed at same point. Did not show tagging fish/SDFN.
- 3-25 RIH w/4-3/4 csg swage bumper sub, jars, 6-3½ DC on 2-7/8 tbg-Tag & swage csg 2883-2901-work swage thru collapse interval several time/POH/RIH w/3-5/8 Impression block on 2-7/8 tbg. Tag fish @ 2901/POH Impression Block showed clean break and open tag/RIH w/2-3/8 center spear (1.948) 1-3-1/8 DC bumper sub jars 6-3½ DC on 2-7/8 tbg/tag & engage fish @ 2901/jar fish op hole 2' to 2899 in 4 hrs. Jarred spear loose from fish/POH.
- 3-26 RIH w/2-3/8 center spear (1.992) 1-3-1/8 DC Bumper Sub jars 6-3½ DC's on 2-7/8 tbg. Tag fish 2901 - Unable to latch/POH w/no Rec/RIH w/3-5/8 impression block on 2-7/8 tbg. Tag fish 2901. POH impression block indicated tbg split/RIH w/ 3-15/16 overshot w/2-3/8 catch exten. Bowl w/Ru & Rite guide & fishing ass'y on 2-7/8 tbg. Tag & latch fish @ 2901 jar 10 min fish pulled free/POH Rec 265' 8-½ jts 2-3/8 tbg- Leaving top of fish 3155. Btm jt flared from shot.
- 3-27 RIH w/4-3/4 csg swage 2-3-1/8 DC Bumper Sub jars 6-3½ DC on 2-7/8 tbg to 400'.