

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PROPOSALS.)

|   |   |
|---|---|
| 1. <input checked="" type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> Dual <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER  | 7. Unit Agreement Name                          |
| 2. Name of Operator<br>Sun Exploration & Production Co. - Midland   | 8. Farm or Lease Name<br>Boyd                   |
| 3. Address of Operator<br>P.O. Box 1861, Midland, Texas 79702   | 9. Well No.<br>5                                |
| 4. Location of Well<br>UNIT LETTER <u>B</u> <u>510</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM<br>THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M. | 10. Field and Pool, or Wildcat<br>Tubb/Drinkard |
| 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County<br>Lea                               |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|  |  |  |   |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>                | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                    | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <u>Run log</u> <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |   |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU workover rig. Install BOP.  
POH w/ 2-3/8" tbg, seal ass'y, seating nipple & sliding sleeve.  
Note: May have sandfill-washover if necessary.  
GIH w/ Homco pkr milling tool w/ six (6) 3 1/2" drill collars on 2-7/8" WS.  
Mill thru Baker Model "D" pkr set at 6145'. (bore size= 2.688").  
POH w/ WS, collars and retrievable portion of pkr.  
GIH w/ WS, RBP. Set RBP at + 6370'.  
Load hole w/ 2% KCL wtr. POH w/ tbg.  
Rig down move out workover rig.  
Rig up Schlumberger. Run Compensated Neutron Log w/ collar locator from 3000' to 6370'.  
Rig down Schlumberger.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp TITLE Acctg. Assist II DATE 1-7-83

APPROVED BY ORIGINAL SIGNED BY TITLE JERRY SEXTON DATE JAN 17 1983  
CONDITIONS OF APPROVAL DISTRICT 1 SUPP