Submit 3 Copies

#### State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office

### OIL CONSERVATION DIVISION

Revisied 1-1-89

_	P.O. Box 2088			
DISTRICT I S				
P.O. Box 1980, Hobbs, NM 88240	anta Fe, New Mexico 87504-2088			
DISTRICT II				
P.O. Drawer Dd, Artesia, NM 88210	API NO. (assigned by OCD on New Wells)			
DISTRICT III	30-025-10450			
1000 Rio Brazos Rd., Aztec, Nm 87410		5. Indicate Type of Lease  STATE  FEE  FEE		
		6. State Oil & Gas Lease No.		
SLINDRY NOTICES	AND DEPOSIT	N/A		
DO NOT USE THE SOME TO THE	AND REPORTS ON WELLS			
- III ENERT NESETIVOIN	SALS TO DRILL OR TO DEEPEN OR PLUG BACK . USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name		
(FORM C-101) FOR 1. Type of Well:	SUCH PROPOSALS.)			
OIL GAS				
wei 🔽				
2. Name of Operator	EK	ELLA		
CHEVRON U.S.A. INC.		8. Well No.		
3. Address of Operator		9. Pool name or Wildcat		
P.O. BOX 1150 MIDLAND, TX 79702 A	BLINEBRY OIL & GAS			
4. Well Location Unit Letter A 66	0 -			
Section 25	O Feet From The NORTH Line and	660 Feet From The EAST Line		
	Township 22S Range 10. Elevation(Show whether DF, RKB, RT, GR, etc.)	37E NMPM LEA County		
11 Check Appropriate R				
NOTICE OF INTENTION TO:	ox to Indecate Nature of Notice, Report, or Othe	er Data		
	SUBSEQUENT R	REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTER CASING		
EMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABAN.		
PULL OR ALTER CASING	CASING TEST AND CMT JOB	abandon & Brunse Dikel		
OTHER:	OTHER: REPAIR TBG LEAR	K, FISH ON/OFF TOOL		
	WELL COMPLETED AS SU	NGLE PRODUCER IN BLINBRY,S.		
12. Describe Proposed or Completed Operations(Clearly state		TOTAL MODULET IN BLINDING.		
esticated date of starting any proposed work) SEE RULE 11	03.			
1410011 00000				
WORK PERFORMED 11-6 THRU				
(WELL FAILED PKR LEAKAGE T	EST 9-25 & 10-28-92). SET PLUG IN	LONG STRING 11 6 02		
DDEC TOT TO FOR DOLLAR		FOUND 9 LUING 11-0-97		

PRES TST TO 500 PSI WITH BLEED OFF TO 0. TBG ON VAC. POH W/SHORT STRING, PICK UP ON LONG STRING & UNABLE TO GET OFF TOOL. RUN FREE PT, TBG STUCK @ 6449. RIH & CUT 2-3/8 TBG @ 6448, WORK DUAL PKR LOOSE, POH & LD LONG STRING & DUAL PKR. TIH TO 6410, RU STRIPPER & PWR SWIVEL, WORK OVERSHOT TO 6447, UNABLE TO GET DEEPER OR ENGAGE FISH. REAM TIGHT SPOT @ 6419, MILL F/6446 TO 6449. UNABLE TO RECOVER FISH. PLUG OUT OF SOUTH BRUNSON DRINKARD (PERFS 6572-7101') WITH PACKER & PLUG @ 6496'. COMPLETED AS SINGLE PRODUCER BY RIH W/PROD STRING & PACKER. TEST TUBING IN HOLE TO 3000 PSI, SET PACKER AT 5471'. ND BOP, NU WHI PLACE WELL ON PRODUCTION.

THE BOT HE VALLE (	JIN PRODU	UCTION			
hereby certify that the information above is true and complete	to the best of	my knowledge and belief.			
SIGNITURE MILLA LIEE	TITLE	TECHNICAL ASSISTANT	DATE:	12/9/92	
E OR PRINT NAME NITA RICE		TELEPHONE NO. (915)687-7436			
g. Signed by  APPROVED BY Paul Kautz  CONDITIONS OF APPROVATER CONDITIONS	TITLE		DATE	DEC 1 1'92	
<b>-</b>					

#### STATE OF NEW MEXICO

## ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

# OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

BRUCE KING GOVERNOR

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

December 7, 1992

Chevron USA Inc. ATT: J.R. Smith P O Box 670 Hobbs, NM 88241

RE: Ella, #1-A, 25-22-37

#### Gentlemen:

Per your conversation with Donna Pitzer of Oil Conservation Division, Hobbs on December 7, 1992 about a Packer Leakage Test on the above listed well, you stated that the casing had collapsed. We need you to move-in on this well immediately and do a workover since this well is a multiple completed in the Blinebry Pool and the Brunson Drinkard Abo South Pool. Your procedure needs to be reported on the form C-103 and mailed to Oil Conservation Division, P O Box 1980, Hobbs NM.

Your allowable will be cancelled effective January 1, 1993 by the Oil Proration Schedule for both zones.

If you have any question, please call the Hobbs office (505) 393-6161.

Yours very truly,

OIL CONSERVATION DIVISION

Jerry Sexton

District I, Supervisor

JS:dp

/cc: Chevron USA Inc, Midland TX ....