

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <u>Chevron U.S.A. Inc.</u> 3. Address of Operator <u>P.O. Box 670, Hobbs, NM 88240</u> 4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <u>3325' CL</u> 12. County <u>Lea</u>	7. Unit Agreement Name 8. Farm or Lease Name <u>Ella</u> 9. Well No. <u>1</u> 10. Field and Pool, or Wildcat <u>Undesignated ABO</u>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Re completion</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WIRU PU. POH with tubing, rods and pump. Set CIBP at 7128 and test to 1000 psi. Squeezed the Drinkard's perms, 6214-6387, with 250 sacks Class "C" cement. Drilled out cement from 5831-7082. Test casing and squeeze to 500 psi. Dumped 14' of cement on CIBP. Perforated from 6572-7101. Acidized with 5000 gals 15% NEFE HCL. Acid fraced with 21,000 gals 20% gelled HCL and 41,000 40# XL gel. The well is flowing on a 20/64 choke.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>M. Casey</u>	TITLE <u>Division Production Engr</u>	DATE <u>7/15/86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	TITLE	DATE <u>JUL 17 1986</u>
APPROVED BY		
CONDITIONS OF APPROVAL, IF ANY:		

74 1000 P.O. 1-10-86

RECEIVED

JUL 16 1986

MOBILE
O.C. OFFICE