

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30 025 10519
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name New Mexico M State
2. Name of Operator GP II Energy, Inc.	8. Well No. 9
3. Address of Operator P. O. Box 50682, Midland, TX 79710	9. Pool name or Wildcat Langlie Mattix SRQ GB SA
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>30</u> Township <u>22S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3425 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Frac Queen Perfs ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9-16-96 - 9-23-96

POH w/rods & tbgs.. RIH w/RBP & set @ 3745'. POH w/tbgs.. Hook up BOP. RIH w/111 jt. 3 1/2" work string. Set pkr. @ 3420'. RU BJ Services. Frac Queen perfs (3502'-3699') w/85000# 16/30 sand & 40000 gal. 50% CO2 @ 30 BPM, avg. tbgs. pressure 3700 PSI. ISIP 1950 PSI. Recovered load water & CO2. POH w/work string. RIH w/2 3/8" tbgs., bailer & retrieving tool 217' sand fill on top of plug. Bail sand. Hit bottom, latch on to plug. Plug released, POH. RIH w/open ended jt., 4' perf sub, & SN @ 3475'. RIH w/pump & rods.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Elaine B. McCarty TITLE Agent DATE 7-27-98

TYPE OR PRINT NAME Elaine B. McCarty TELEPHONE NO 915/684-4748 EXT 5

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAM
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 16 1998

CONDITIONS OF APPROVAL, IF ANY: