| | • | | |
|---|--|--|---|
| NO. OF COPIES RECEIVED | | | Form C-103 |
| DISTRIBUTION | | | Supersedes Old |
| SANTA FE | | SERVATION COMMISSION | C-102 and C-103 Effective 1-1-65 |
| FILE | | lu 20 - | Ellective 1-1-02 |
| U.S.G.S. | | JUL 28 9 36 AM JOR | 5a. Indicate Type of Lease |
| LAND OFFICE | | JUL 28 9 36 AM '65 | State X Fee |
| OPERATOR | | | 5. State Oil & Gas Lease No. |
| | <u>_</u> | | B-934 |
| (DO NOT USE THIS FORM FOR USE "APPLI | DRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG E CATION FOR PERMIT -" (FORM C-101) FOR SUC | WELLS BACK TO A DIFFERENT RESERVOIR. + PROPOSALS.) | |
| 1 | Water Injection | Well in Langlie-Mattix | 7. Unit Agreement Name |
| OIL GAS WELL WELL | OTHER- Water Flood Syste | em. | _ |
| 2. Name of Operator | | | 8. Farm or Lease Name |
| Humble Oil & Refir | ning Company | | New Mexico, State 秤 |
| 3, Address of Operator | | | 9. Well No. |
| Box 2100, Hobbs, I | New Mexico 88240 | | 31 |
| 4. Location of Well | | | 10. Field and Pool, or Wildcat |
| UNIT LETTERA | 660 FEET FROM THE North | LINE AND 660 | Langlie-Mattix |
| | | | |
| THE East LINE, SE | CTION 30 TOWNSHIP 22-S | BANGE 37-E | |
| · · · · | | | |
| | 15. Elevation (Show whether | DF, RT, GR, etc.) | 12. County |
| | 3401 | DF | Lea |
| Chec | k Appropriate Box To Indicate N | lature of Notice, Report or Of | her Data |
| | INTENTION TO: | | T REPORT OF: |
| | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON | _ | COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | CHANGE PLANS | CASING TEST AND CEMENT JOB | |
| | • | OTHER #Additional Reco | very Area |
| OTHER | · | R-2891 of 4-8-6 | |
| 17. Describe Proposed or Completed | Operations (Clearly state all pertinent dete | aile and give norticant datas is 1 1 | |
| | operations (occurry state are pertitent det | ano, and give pertinent autes, including | g estimated date of starting any proposed |

work) SEE RULE 1103.

Move in and rig up company unit. Bled pressure off well. Unseated packer. Pulled packer and tubing. Perf. 2-7/8" casing at 3591, 3593, 3600, 3627, 3632, 3647, 3648, and 3651 with one radio active jet shot per depth. Found bottom at 3683. Set Halliburton retrievable bridge plug at 3665. Reset plug at 3663. Failed to shut off water. Moved company unit off well. Moved in contract unit. Pulled retrievable bridge plug up above perforations and set in blank pipe. Found communications between perforations. Pulled retrievable bridge plug out of hole. Released contract unit. Moved in company unit. Rigged up and ran tubing. Washed to bottom (3738). Came out of hole. Reran tubing and Camco packer. Set packer at 3572. Placed well on injection. Well recompleted as a water injection well thru perf. 3591, 3593, 3600, 3627, 3632, 3647, 3648, 3651, 3680-05, 3702-05.

| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | | |
|--|-------------------------|--------------|--|--|--|
| SIGNED | TITLE Dist. Adm. Supvr. | DATE 7-27-65 | | | |
| APPROVED BY | | | | | |
| CONDITIONS OF APPROVAL, IF ANY: | TITLE | DATE | | | |