

Submit 3 Copies
to Appropriate
District Office

District I
P.O. Box 1980, Hobbs, NM 88240

District II
P.O. Drawer DD, Artesia, NM 88210

District III
1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.	30 - 025 - 10541
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-3480'
7. Lease Name or Unit agreement Name	SKELLY PENROSE B UNIT
8. Well No.	13
9. Pool name or Wildcat	LANGLIE MATTIX 7 RVR Q-GB

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator OXY USA INC.	
3. Address of Operator P.O. Box 50250 Midland, TX 79710	
4. Well Location Unit Letter M : 990 Feet From The SOUTH Line and 990 Feet From The WEST Line Section 32 Township 22 S Range 37 E NMPM LEA County	
10. Elevation (Show whether DF, AKB, RT, GR, etc.) 3,390	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒ ✓
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 4003' PERFS - 3660' - 3792'

MIRU PU 6/22/93, NDWH, NUBOP, RIH & TAG @ 3635', CO TO 3854'. RIH W/ CIBP SET @ 3585', RIH & SPOT 25SX CL C CMT W/ 2% CACL2 ON TOP OF CIBP 3585' - 3345'.. CIRC HOLE W/ MUD-LADEN FLUID, POOH SPOT 25 SX CL C W/ 2% CACL2 PLUG FROM 2682'-2442''. POOH, PERF 2 HOLES @ 1300', M&P 125SX CL C CMT W/ 2% CACL2, SQZ TO 450#, WOC. RIH & TAG TOC @ 361', M&P 160SX CL C CMT W/ 2% CACL2, CIRC 70SX TO PIT, CMT TO SURFACE. RDPU 7/1/93. REMOVE WH, INSTALL DRY HOLE MARKER. WELL P&A'D 7/2/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 09 03 93
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 14 1999

g/c

RECEIVED

SEP 07 1993

LIBRARY